

ADA TITLE II TRANSITION PLAN

prepared for

Sonoma County Library Headquarters
6135 State Farm Drive
Rohnert Park, CA. 94928
Suzanne Silva, ADA Coordinator



PREPARED BY:

Bureau Veritas
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.us.bureauveritas.com

BV CONTACT:

Matthew Anderson
Program Manager
800.733.0660 x7613
Matt.Anderson@bureauveritas.com

BV PROJECT #:

142143.21R000-00A.206

DATE OF REPORT:

May 26, 2022

ADA TITLE II TRANSITION PLAN
OF

SONOMA COUNTY LIBRARY HEADQUARTERS
6135 STATE FARM DRIVE
ROHNERT PARK, CA 94928

Bureau Veritas

TABLE OF CONTENTS

- 1. CERTIFICATION..... 2**
- 2. PURPOSE AND SCOPE..... 3**
 - 2.1 Overview of the Sonoma County Library..... 3
 - 2.2 Purpose of the Transition Plan 4
 - 2.3 Basis for Probable Costs 4
 - 2.4 Scope of Work 4
 - 2.5 Physical Barrier Assessments 4
- 3. ACCESSIBILITY REQUIREMENTS 6**
- 4. COMPLIANCE STRATEGY 7**
- 5. PRIORITIES 8**
 - 5.1 Facility Priorities 8
 - 5.2 Barrier Priorities 8
- 6. SONOMA COUNTY LIBRARY FUNDING LEVELS..... 10**
- 7. TRANSITION PLAN COMPONENTS 11**
 - 7.1 Overview..... 11
 - 7.2 System Barrier Summary 12
 - 7.3 Barrier Removal Strategy 13
 - 7.4 Conclusion 14
- 8. APPENDICES 15**



1. CERTIFICATION

Bureau Veritas has completed a Comprehensive Accessibility Evaluation of the Sonoma County Library properties in Sonoma County, California, in accordance with the requirements of 28 CFR Part 35, the 2010 ADA Design Standards for Accessible Design, and the State of California Building Code sections related to accessibility.

The conclusions and recommendations presented in this report are based on the evaluations of properties under the jurisdiction of the Sonoma County Library, associated documentation related to the properties, and input from the Sonoma County Library staff.

The conclusions and recommendations presented in this Transition Plan report are based on the evaluations of properties under the jurisdiction of Sonoma County Library.

Accessibility evaluations were conducted by Bureau Veritas Project Architects and Project Engineers during site visits to individual properties. Project Architects' and Engineers' observations were made during site visits conducted from September 21, 2021 through October 12, 2021. Cost estimates for barrier removal are planning level cost estimates based on Bureau Veritas's experience with similar properties.

The assessments were performed at the Client's request using methods and procedures consistent with good commercial and customary practice for assessing compliance with the Title II provisions of the Americans with Disabilities Act (ADA), including the requirements of 28 CFR Part 35, and applicable state requirements. Accessibility barriers in areas which were not readily accessible, and/or may not have been visible, may exist. Individual facility reports describe property conditions at the time that the observations and research were conducted. The individual facility reports are not an engineering evaluation of physical conditions. The Self-Evaluation did not include engineering evaluations or engineering calculations to determine the adequacy of the park or facility's original design or to determine engineered cost estimates.

The opinions Bureau Veritas expresses in this report were formed utilizing the degree of skill and care ordinarily exercised by any prudent architect or engineer in the same community under similar circumstances. Bureau Veritas assumes no responsibility or liability for the accuracy of the information contained in this report, which has been obtained from the Client or the Client's representatives, from other interested parties, or from the public domain. The conclusions presented represent Bureau Veritas's professional judgment based on information obtained during the course of this assignment. The conclusions presented are based on the data provided, observations made, and conditions that existed specifically on the date of the assessments of individual properties.

Bureau Veritas certifies that Bureau Veritas has no undisclosed interest in the subject property, Bureau Veritas' relationship with the Client is at arms-length, and that Bureau Veritas' employment and compensation are not contingent upon the findings or estimated costs to remedy any deficiencies.

This report has been prepared on behalf of and exclusively for the use of the Sonoma County Library for the purposes stated herein. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and Bureau Veritas.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of Bureau Veritas. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to Bureau Veritas.

If you have any questions regarding this report, please contact Matthew Anderson, Senior Engineering Consultant, (800) 766-0660 x 7613.

Certified by:



Kurt Hagen

Kurt.Hagen@bureauveritas.com

2. PURPOSE AND SCOPE

2.1 Overview of the Sonoma County Library

The mission statement of the Sonoma County Library is: Our mission is to bring information, ideas, and people together to build a stronger community.

The Sonoma County Library Headquarters are located in Rohnert Park and provide the center of operations and administration for the countywide Sonoma County Library System. The Office of Director of the Library is located in the Rohnert Park headquarters as well as providing offices and working space for the Budget and Finance Department, Human capital resources, Collection Services and Facilities.

Sonoma County Library is governed by Library Administration, Library Commission and Library Advisory Boards under a Joint Powers Agreement (JPA). The head of the Library Administration is Library Director Ann Hammond. The Library is governed by an independent 11 member Library Commission as specified in the revised Joint Powers Agreement. The city councils of Cloverdale, Cotati, Healdsburg, Petaluma, Rohnert Park, Santa Rosa, Sebastopol, Sonoma, and Windsor, along with the Sonoma County Board of Supervisors, each appoint a Library Commissioner. The City of Santa Rosa and the Sonoma County Board of Supervisors also jointly appoint one Library Commissioner.

The Commission generally meets monthly, with additional special meetings as needed. Meetings are open to the public and the public is welcome to attend.

Current Library Administration consists of thirteen (13) staff members. Sonoma County Library has added the equivalent of 3.75 new staff FTEs.

The Sonoma County Library facilities occupy 187,334 FT.².

Physical amenities currently available within the Sonoma County Library system are:

AMENITY SUMMARY		
FACILITY	AMENITIES	SQUARE FOOTAGE
Central Library	Two (2) Book Clubs, Williams Overture 2 88-key console digital piano.	61,800
Cloverdale Library	Two (2) Book Clubs, ADA parking lot upgrade, technology additions.	7,200
Guerneville Library	Two (2) Book Clubs	6,237
Healdsburg Library	Two (2) Book Clubs, 3D printing services	11,700
Northwest Santa Rosa Library	11 one hour Internet computers, one 15 minute express computer, three catalog computers, one copier (black-and-white \$.15 and color copies \$.50), one public printer (\$5 free printing), 3D printer. For children, there are three one hour, Internet computers, to children's game computers, and one catalog computer.	7,224
Petaluma Library	One (1) Book Club, 3D printing services	26,766
Rincon Valley Library	One (1) Book Club, 3D printing services	15,000
Rohnert Park-Cotati Library	Two (2) Book Clubs	23,807

AMENITY SUMMARY		
Sebastopol Library	Five (5) Book Club, 3D printing services	10,000
Sonoma Valley Library	Two (2) Book Clubs	10,000
Windsor Library	N/A	7,600
Total Number of Amenities		187,334 ft.²

2.2 Purpose of the Transition Plan

The purpose of this Transition Plan is to plan accessibility compliance for the Sonoma County Library with the requirements of Title II of the Americans with Disabilities Act (ADA) and applicable state regulations contained in the accessibility and related chapters of the California Building Code. The Transition Plan is part of the Self-Evaluation process required of Title II entities (state and local public agencies).

2.3 Basis for Probable Costs

The estimates for the repair and capital reserves items noted within this report are summarized in Section 3, and individual observation details are provided in Appendix A.

The estimates are based on invoice or bid documents provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means* and *Marshall & Swift*, Bureau Veritas' experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions. Typically, barrier removal allowances are based upon the removal of the specific element being evaluated (for example, parking stalls, curb ramps, ramps). Grading plans based on field surveys using land surveyor instrumentation could result in significantly different material quantities and subsequent higher project costs. Bureau Veritas has no control over the final scope of work, pricing methods, and costs associated with a contractor constructing the project. The opinion of probable costs within this report cannot guarantee that the costs will accurately reflect the actual bids for construction.

2.4 Scope of Work

A Self-Evaluation is a governmental organizations' evaluation of its current services, policies and practices, and all physical facilities. The Self Evaluation comprises three components:

- Data gathering: assessments of individual physical properties and internal reviews of public services and programs, communications, and employment practices
- Transition Plan based on the physical and programmatic assessments
- Action necessary to make required additions or modifications to non-compliant elements

This Transition Plan represents the planned modifications to programs and physical facilities provided by the Sonoma County Library. The Transition Plan is a summation and analysis of the barriers to use of facilities.

2.5 Physical Barrier Assessments

A Bureau Veritas Subject Matter Expert visited each property within the Sonoma County Library to evaluate the facilities in accordance with the ADA and State of California Building Code and assess the existing property improvements' compliance with the Title II provisions of the Americans with Disabilities Act (ADA) and applicable state requirements.

The field observer conducted a thorough review of the facility to observe and identify barriers to accessibility and formulate recommendations to remedy the physical barriers. As a part of the review, the field observer met with a property representative with specific knowledge of the facility to gain a clear understanding of overall features, public use patterns, and relevant historical data. All features of the property are subject to observation, which includes but is not limited to parking lots, sidewalks, access ramps, and all common areas accessible to the public, as well as employee areas.

During the site walk-through, the field observer followed a Survey Form that meets or exceeds the current ADAAG format and utilized a digital level, measuring tape, pressure gauge, and digital camera. The field observer identified and prioritized any existing improvements not in accordance with the applicable ADA requirements in the order of preference as set out by the DOJ in general categories, and refined by Bureau Veritas.

The Bureau Veritas team assessed exterior and interior in order to identify existing conditions that are not in accordance with the applicable regulations. Examples of elements required to be accessible are:

- Parking- adequacy as to automobile number, van accessible number, signage, and markings
- Parking and passenger loading zones
- Accessible routes: sidewalks and paths, interior routes
- Space allowance and ranges
- Protruding objects
- Ground and floor surfaces
- Curb and other ramps; size, distance, slope, rails, and surface finishes
- Exterior and interior common stairs
- Platform lifts (wheelchair lifts)
- Entrances and exits to common areas and employee areas
- Handrails and grab bars
- Alarms (visual and audible) and warnings
- Signage, Braille, and visual
- Switches and outlets

Individual assessment reports for each property surveyed included:

- Summary of Findings for all amenity features (parking stalls, curb ramps, paths of travel, etc.)
- Individually recorded barriers
- Digital photos of observed deficiencies and representative photos of elements observed to be in compliance
- Geocode GPS references for the location of observed deficiencies
- Applicable ADA and State of California regulatory references
- Recommendations for viable corrective measures necessary to comply with regulations
- Planning level cost estimates for each barrier

Assessment results were tabulated into an ADA database using AssetCALC™, an online interactive database created by Bureau Veritas to manage ADA and state accessibility code information. The AssetCALC™ asset management database used by Bureau Veritas establishes an online database in www.Assetcalc.net, which is used to compile records of all deficiencies and accessibility barriers, store photos, and documents related to the individual facilities, and create reports. AssetCALC™ provides the ability to list, prioritize, query, and track accessibility barrier removals. Cost data in the database is calculated using rounding. Any minor discrepancies in the costs shown in this report are the result of rounding.

3. ACCESSIBILITY REQUIREMENTS

The Americans with Disabilities Act (ADA) of 1990 provides comprehensive, wide-ranging rights and protections to individuals with disabilities in the areas of employment, public accommodations, state and local government services, and telecommunications. Many consider it to be one of the most important civil rights laws since the Civil Rights Act of 1964. The goal of the ADA is to ensure equality of opportunity, full participation, and independent living to all individuals, including those with disabilities; it expressly prohibits all state and local governments and most private businesses from discriminating on the basis of disability. The ADA provides a clear and comprehensive national mandate for the elimination of discrimination against individuals with disabilities. The ADA includes the definition of a disability, and in 2008, the ADA Amendments Act expanded and better defined the definition of a disability.

The ADA defines a disability, with respect to an individual, in one of three ways: a physical or mental impairment that substantially limits one or more major life activities; a record or history of such impairment; or regarded as having such as an impairment. Major life activities include, but are not limited to, caring for oneself, performing manual tasks, seeing, hearing, eating, sleeping, walking, standing, lifting, bending, speaking, breathing, learning, reading, concentrating, thinking, communicating, and working.

The ADA is divided into 5 Titles: Employment, Public Services, Public Accommodations and Commercial Facilities, Telecommunications, and Miscellaneous Provisions. This report focuses on the Title II requirements.

The Department of Justice (DOJ) is responsible for the enforcement of the provisions of the ADA other than employment policy related issues. The United States Department of Justice's regulations implementing Title II of the ADA dictate that local governments and public agencies such as [Agency Name](#) must evaluate their services, programs, policies, and practices and identify barriers that may limit accessibility for individuals with disabilities and develop transition plans describing how they will address identified barriers.

In 2010, the Department of Justice issued revised and expanded ADA regulations. The new regulations revised and updated earlier standards as well as included new standards for various recreational uses such as play equipment, amusement rides, fishing piers, etc. These are collectively called the 2010 ADA Standards for Accessible Design (the "2010 Standards"). These new standards guide all new park construction and renovation projects. All facilities and parks have been evaluated and audited using the 2010 Standards.

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by public entities to access and use of on the basis of disability. In addition, public agencies must provide program access to all programs of the agency. Program, as used in the phrase "program access", is defined by the Department of Justice as "programs, facilities, and activities" of the public agency. Regardless of their age, programs, facilities, and activities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. However, program access by the public is still required.

A full explanation of the ADA is located in Appendix A.

4. COMPLIANCE STRATEGY

The proposed strategy for ADA compliance is a multi-phase approach for facility access as well as programmatic access. The goal of this strategy is to ensure that the programs, services, and opportunities offered by Sonoma County Library are accessible to the citizens of the Sonoma community, regardless of abilities, yet provide a realistic plan for barrier removal, which is within the fiscal capabilities of the Sonoma County Library.

The provision of facility access is proposed to be based on a facility level, with the initial focus on the highest use properties. As its foundation, the proposed strategy is to ensure amenities which are in highest demand are accessible, subject to various limitations such as technically infeasible conditions and funding limitations. The strategy takes into account numerous factors such as population density, usage levels, amenity uniqueness, and other factors. This strategy will enable the best use of available funds to provide the optimal facility access to the library programs for all citizens.

Programmatic access will be an ongoing effort. Solano County Library will initiate efforts to improve facility access, develop, and expands its review of its many programs with a focus on policy initiatives, inclusion, and reasonable accommodation needs. Not all barriers must be removed, as long as the disabled community is accommodated, and the unique programs, facilities, and services are made available for users with disabilities. Selected recurring amenities will be made barrier-free, so that at least one of each type of amenity is accessible.

The level of funding is expected to continue at the same level going forward. Therefore, the majority of barrier removal is not anticipated to be funded as a separate initiative, but rather as part of larger capital projects. Barrier removal must be accomplished in phases, as funding becomes available.

5. PRIORITIES

5.1 Facility Priorities

The Sonoma County Library has established an accessibility priority rating for facilities using public usage criteria. Usage rates were determined by general visual observation by Solano County Library staff. Priorities by level of community usage of individual facilities are:

Phase 1

1. Petaluma Library
2. Rincon Valley Library
3. Healdsburg Library

Phase 2

1. Northwest Santa Rosa Library
2. Sonoma Valley Library
3. Cloverdale Library

Phase 3

1. Guerneville Library
2. Rohnert Park-Cotati
3. Sebastopol Library

Phase 4

1. Central Library
2. Windsor Library

The number of amenities, services, and programs available at a facility are primary factors affecting facility usage levels. Distance required to travel from residences, proximity to public transportation, and safety are secondary factors affecting usage.

5.2 Barrier Priorities

The scope of the individual assessments were limited to exterior site features and amenities, specifically accessible parking and exterior accessible pedestrian paths of travel to and from all amenities and features provided at each site. Elements assessed included amenities such as parking, playgrounds, and restroom interiors. Bureau Veritas prioritized each of the captured barriers based on Department of Justice (DOJ) criteria focusing on the primary scope of work. Interior spaces such as common corridors, public restrooms, and other interior elements along the common path of travel, such as water fountains, that are the responsibility of the property owner, were included.

Per DOJ Guidelines, *people with disabilities should be able to arrive on the site, approach the building or facility and its amenities, and enter as freely as everyone else.*

The following priority levels have been used to assign priorities to barriers within each property and facility.

Priority 1: Path of Travel-

Accessible Van Parking – Access to a public facility begins with accessible parking. Van accessible parking is deemed the most important barrier. Those with the most severe disabilities tend to require a van accessible space to accommodate their vehicle and mobility device. In addition, when only the minimum number of accessible spaces is required, it must be a van accessible space. This priority includes all barriers associated with the compliance of a van accessible space including signage, restriping, constructing or reconfiguring the pavement to accommodate the required number of spaces.

Accessible Car Parking – Access to a public facility begins with accessible parking. Car accessible parking is deemed the second most important barrier. This priority includes all barriers associated with the compliance of a van accessible space including signage, restriping, constructing or reconfiguring the pavement to accommodate the required number of accessible spaces.

Accessible Approach and Entrances – A public agency is required to take measures to provide access to a place of public accommodation and employee areas from public sidewalks, parking, or public transportation. The DOJ dictates the minimum width, cross and running slope, signage, and handrail requirements associated with pedestrian accessible routes of travel. These measures include, for example, installing an entrance ramp, correcting tripping hazards or lessening the slope of a curb ramp. At least one route of travel to each amenity or feature should be safe and accessible for everyone, including people with disabilities.

Priority 2: Elements used for programs, services, and activities- Barriers may include play equipment, picnic tables, public counters, benches, and trash receptacles.

Priority 3: Restrooms, Signage - Barriers may include widening of toilet stalls, installation of grab bars, and lowering lavatories and mirrors.

Priority 4: Access to Auxiliary Features and Amenities – A public agency is required to take measures to provide access to auxiliary features and amenities along paths of travel, for instance, kiosks, water fountains, and kitchen appliances.

Priority 5: Employee-only Areas- Employee-only areas are required to have accessible entrances and exits, and accessible paths of travel within interior work areas and work stations. Corridors in employee-only areas, employee-only restrooms, employee-only kitchens and employee-only break rooms are considered public areas (rather than employee-only areas) under the ADA, and therefore, are required to fully comply with accessibility regulations governing those types of areas.

Employee areas have been set as the lowest priority, due to the fact that the total estimated cost for barrier removal in public areas is the more pressing need.

Some of the existing accessibility barriers require a minimal amount of effort or expense to remove, and are found throughout the system. These types of barrier removals are called “Low Hanging Fruit,” or easy barrier removal. “Low hanging fruit” is defined as accessibility barrier removal which can be incorporated into recurring work being completed on a life cycle basis, and which is relatively low in cost.

6. SONOMA COUNTY LIBRARY FUNDING LEVELS

The total amount of revenue in the 2021-2022 budget was approximately \$43,222,142. The majority of the funds are allocated to expenses not related to physical facility improvements, such as wages, insurance, equipment, and other program expenses. The existing revenue level is not anticipated to increase significantly in the future.

The 2021-2022 Year budget amount of the General Fund was approximately \$21,040,431. The Solano County Library generates its funding from sources under the General Fund:

Expenses in the 2021-2022 fiscal year for Capital Projects were approximately \$2,590,920.

Based on the information above, the annual funding level for barrier removal can be no greater than the funds available for Capital Projects at a maximum, although some barriers may be removed through maintenance project funds, such as “low hanging fruit”.

7. TRANSITION PLAN COMPONENTS

7.1 Overview

The 2022 Transition Plan is a snapshot in time to evaluate and prioritize accessibility barrier removal throughout the Sonoma County Library system. The Transition Plan will be a living document and not a static view of the existing state of ADA compliance at the Sonoma County Library. As such, it can be modified and updated on a periodic basis to reflect barrier removal efforts, changes in economic conditions, new and revised strategies, and reflect future public input.

The Transition Plan is a flexible document, as strategies, priorities, and funding opportunities change. Sonoma County Library demographics may vary from the current demographic composition of Sonoma County. Public preferences for library services may change, while funding priorities and funding levels may change as well.

The Transition Plan will require modification as conditions and priorities are changed, new ADA requirements are issued by DOJ, and/or unanticipated policy, or fiscal needs shifts occur. To further complicate the difficulty of setting priorities, the Solano County Library system is intertwined with other entities, such as Solano County, so that funding for corrective actions on facilities extends beyond the immediate control of its own boundaries.

As the ADA Coordinator, Suzanne Silva, for Sonoma County Library, is responsible for updating, Sonoma County Library's Transition Plan. At a minimum of at least once a year, the Transition Plan should be updated, noting the barriers removed and any changes to the funding noted. Suzanne Silva can be reached at (707) 545-0831 or ssilva@sonomalibrary.org.

7.2 System Barrier Summary

The removal of all identified physical accessibility barriers in the system is estimated to cost \$1,933,254. The existing barrier planning level cost estimate totals are summarized in Table 7.2 below:

Facility / Building	Priority 1		Priority 2		Priority 3		Priority 4		Priority 5		Total	
	Est. Cost	Items	Est. Cost	Items	Est. Cost	Items	Est. Cost	Items	Est. Cost	Items	Est. Cost	Items
Central Library	\$150,570	45	\$64,378	19	\$143,060	34	\$229,331	9			\$587,339	107
Cloverdale Library	\$40,437	11	\$22,473	9	\$46,554	14	\$1,946	2			\$111,411	36
Guerneville Library	\$71,075	30	\$15,009	11	\$10,150	15	\$2,472	3			\$98,707	59
Healdsburg Library	\$61,754	36	\$27,110	19	\$45,766	23	\$3,916	4			\$138,546	82
Northwest Santa Rosa Library	\$74,731	24	\$11,838	14	\$13,028	17	\$368	1			\$99,964	56
Petaluma Library	\$142,831	44	\$22,772	17	\$163,571	25	\$4,967	7			\$334,141	93
Rincon Valley Library	\$147,138	36	\$30,984	21	\$13,779	12	\$7,971	7			\$199,871	76
Rohnert Park-Cotati Library	\$78,679	20	\$36,594	11	\$34,816	26	\$3,390	5			\$153,479	62
Sebastopol Library	\$89,199	19	\$6,939	11	\$12,485	19	\$921	2			\$109,544	51
Sonoma Valley Library	\$21,881	8	\$8,455	5	\$8,879	8					\$39,215	21
Windsor Library	\$19,712	11	\$14,389	9	\$26,411	22	\$526	1			\$61,037	43
Grand Total	\$898,006	284	\$260,941	146	\$518,499	215	\$255,807	41	\$0	0	\$1,933,253	686

For the accessibility summaries of individual facilities, see Appendix B.



7.3 Barrier Removal Strategy

The Sonoma County Library has adopted a multi-phase strategy using the ranking criteria of facility usage levels to determine the phases for barrier removal. The long-term goal is to make all unique amenities and at least one of each type of recurring amenity accessible. In order to meet the programmatic requirement for accessibility of programs, facilities, and services to the disabled by local agencies, the District will make accommodations for the disabled when requested. For further explanation of the obligations of a public agency, see Appendix A, section 1.2.1.

The planned phases for barrier removal and planning level cost estimates for each phase are summarized below.

Phases	Estimated Cost	Barriers
1. Petaluma Library	\$334,141	93
1. Rincon Valley Library	\$199,871	76
1. Healdsburg Library	\$138,546	82
TOTALS	\$672,558	251
2. Northwest Santa Rosa Library	\$99,964	56
2. Cloverdale Library	\$111,411	36
2. Sonoma Valley Library	\$39,215	21
TOTALS	\$250,590	113
3. Rohnert Park-Cotati Library	\$153,479	62
3. Sebastopol Library	\$109,544	51
3. Guerneville Library	\$98,707	59
TOTALS	\$361,730	172
4. Central Library	\$587,339	107
4. Windsor Library	\$61,037	43
TOTALS	\$648,376	150
Totals	\$1,933,254	686

NOTE: Due to rounding, the totals shown in this table and the individual tables in the Appendices differ from Table 7.2, System Barrier Summary, and the tables in the AssetCalc management database by approximately \$260.

See Appendix C for the full listing of barriers in each phase.

7.4 Conclusion

The establishment of planned phases for barrier removal is determined by the criteria adopted by Sonoma County Library, the regulations of the Americans with Disabilities Act, and by the necessity to schedule barrier removals within an established framework. The timing of the completion of each phase of barrier removal is subject to a number of factors. The framework timeline will be determined by the following factors, as well as potential unknown additional factors, which will determine any changes to and specificity of the Transition Plan, which may be required in future years:

- Funding sources and funding timelines
- Level of ADA barrier removal, with the highest ranking given to the highest use areas
- Opportunity to combine ADA barrier removal with scheduled capital improvements, such as playground replacements, parking lot renovations, restroom repairs or park reconstruction
- Development of a work program to eliminate “low hanging fruit” (easily removed barriers)
- Realistic time frame for accomplishment based on fiscal capability
- Demographic distributions
- Input from the community

Planning level estimated values for barrier removal will change over time due to inflation, changes in construction practices and materials, and unanticipated changes or additions to accessibility regulations. It is expected that the total cost of required accessibility barrier removal will change over time due to the completion of individual barrier removal efforts and due to funding of capital projects which incorporate barrier removal in the immediate and distant future.

8. APPENDICES

Appendix A - ADA Title II Requirements

Appendix B - Accessibility Summaries by Facility

APPENDIX A

ADA TITLE II REQUIREMENTS

The Americans with Disabilities Act

With the passage of the Americans with Disabilities Act in 1990, people with disabilities were, for the first time, assured of access to all programs and services provided by state and local government agencies. Previously, under Section 504 of the Rehabilitation Act of 1973, as amended, only those public entities that receive federal funding were explicitly prohibited from discriminating on the basis of disability. Title II of the Americans with Disabilities Act applies Title I regulations to most public entities and became effective on January 26, 1992.

The Americans with Disabilities Act is divided into five areas, Titles I through V.

Title I- Employment: Title I of the Americans with Disabilities Act prohibits all employers, including government agencies, from discriminatory practices in the hiring, training, advancement, compensation, or discharge of any employee, or in any terms, conditions, and rights of employment.

Title II- Public Services: Title II of the American Disabilities Act, which governs state and local government entities, prohibits all public entities, even those completely independent from federal funding, from discriminating against people with disabilities. Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by state and local government entities to access and use of “areas of public accommodations” and “public facilities” on the basis of disability.

Title III- Public Accommodations and Commercial Facilities: Title III requires places of public accommodation (privately funded and operated facilities) and commercial facilities that serve the public to be accessible to and usable by people with disabilities.

Title IV- Telecommunications: Title IV covers private telecommunication carriers offering services to the public to increase the availability of interstate and intrastate telecommunication relay services to individuals with hearing and speech impairments.

Title V- Miscellaneous Provisions: Title V contains miscellaneous provisions, including construction standards and practices, provisions for attorneys’ fees, and technical assistance provisions.

Terms such as “Public Entity” and “Governmental Agency” are applicable to Title II entities, which are defined as state and local governments.

The Department of Justice (DOJ) is tasked with enforcement of the ADA.

Scope of Title II

Title II is divided into two subtitles. This discussion focuses only on Subtitle A, which is implemented by the Department of Justice’s Title II regulation at 28 CFR § Part 35. Subtitle B covers public transportation and is implemented by the Department of Transportation’s regulation. Subtitle B provisions are not applicable to this report, since parks are not a mode of public transportation. The use of the term “Title II” anywhere in the Transition Plan report refers only to Subtitle A.

28 CFR §35.102 Application

(a) Except as provided in paragraph (b) of this section, this part applies to all services, programs, and activities provided or made available by public entities.

(b) To the extent that public transportation services, programs, and activities of public entities are covered by Subtitle B of Title II (42 U.S.C.12141) of the ADA, they are not subject to the requirements of this part.

The obligation to comply with Title II extends to all public entities, including:

- Any state or local government

- Any department, agency, special purpose district, or other instrumentality of a state or local government

All local agencies, including municipalities, are required to comply with Title II because they are considered “instrumentalities” of the state government. All programs, activities, and services of local government, including municipalities, must be in compliance with Title II. Examples of activities covered include:

- The operation of all services and programs offered by the entity;
- All aspects of the employment relationship; and
- Services carried out by contractors.

Title II covers any and all events the local government system offers, for example, any public meetings, entertainment or lecture series, all events offered by the school system including after-school activities and social events, festivals or other special events, and all services provided for the public or staff. Services provided by any private contractors on behalf of the municipal system must also comply fully with relevant provisions of Title II.

Under Title II, a public entity (i.e. governmental agency) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities. The local government may not deny the benefits of its programs, activities and services to individuals with disabilities because its facilities are inaccessible.

Public meeting rooms must be accessible to people with disabilities. Buildings where public meetings, services, programs or activities take place must provide access to telephones and restrooms, if provided, for people with disabilities as well as the general public. When a program, service or activity is scheduled in an inaccessible location and a person with a disability notifies the agency of their desire or need to participate, that program, service or activity must be moved to an accessible location.

The government must maintain equipment and features of facilities in working order, if those features and equipment are required to provide ready access to individuals with disabilities. Isolated or temporary interruptions in access due to maintenance and repair of accessible features are not prohibited. For example, where the governmental agency must provide an accessible route, the route must remain accessible and not blocked by obstacles such as furniture, filing cabinets, or potted plants. An isolated instance of placement of an object on an accessible route, however, would not be a violation if the object is promptly removed. Similarly, accessible doors must be unlocked when the governmental agency's offices are open for business.

Mechanical failures in equipment such as elevators or automatic doors will occur from time to time. The obligation to ensure that facilities are readily accessible to and usable by individuals with disabilities would be violated if repairs are not made promptly or if improper or inadequate maintenance causes repeated failures.

However, this does not --

- (1) Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities;
- (2) Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or

(3) Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

In summary, Title II requires state, county, and city governments to ensure that all of their programs, services, and activities, when viewed in their entirety, are accessible to people with disabilities. Program access is intended to remove physical barriers to state, county, and city services, programs, and activities, but it generally does not require that a government agency make each facility, or each part of a facility, accessible. For example, all restrooms in a facility may not be accessible. However, signage directing people with disabilities to the accessible features and spaces in a facility, including at least one accessible restroom, should be provided.

Program accessibility may be achieved in a variety of ways. State, county, and city governments may choose to make structural changes to existing facilities to achieve access, or can pursue alternatives to structural changes to achieve program accessibility. For example, governments can move public meetings to accessible buildings, or can relocate services for individuals with disabilities to accessible levels or sections of buildings. When choosing between possible methods of program accessibility, governments must give priority to the choices that offer services, programs, and activities in the most integrated setting appropriate. [28 C.F.R. § 35.149, 35.150, 35.151, 35.163]

Definition of Disability

The ADA stipulates a three-pronged definition of disability. Disability is defined as an individual who:

- Has a physical or mental impairment that substantially limits one or more major life activities; or
- Has a record or history of such an impairment; or
- Is perceived or regarded as having such an impairment;
- Major life activities encompasses activities such as caring for oneself, performing manual tasks, walking, seeing, hearing, speaking, breathing, learning and working. [28 CFR § 35.104]

Human Resources

The ADA requires equal opportunity for the disabled in all areas of employment practices, including the application process, interviewing, testing, hiring, job assignment, evaluation, discipline, medical examinations, compensation, promotion, on-the-job training, layoff/recall, termination, leave and benefits such as health insurance. The non-discrimination requirement applies to the hiring process, as well as employees.

The ADA requires that all employees be provided equal access to benefits, such as health insurance, regardless of disability. However, the regulations also indicate that certain restrictions, such as pre-existing condition waiting periods or caps on particular types of services, such as out-patient physical therapy, are permissible unless proven to be a subterfuge for discrimination.

The ADA requirements for the hiring protocol and all areas of responsibility of the human resources department extend to seasonal workers, workers covered by collective bargaining agreements and works who may be hired through outside agencies. Volunteers, interns or student teachers who may be placed at an agency program or recruiters are not necessarily defined as government employees.

An important factor in the Self-Evaluation process is the identification of unionized employees and the terms of union agreements. For example, the terms of a collective bargaining agreement may include job restructuring or reassignment requests, which may affect seniority provisions. If the granting of requests would create an undue hardship, the Equal Employment Opportunity Commission (EEOC) has the authority to determine on a case-by-case basis whether the claim of undue hardship is valid.

Employment regulations treat alcohol and drug use differently. Alcoholism is recognized as a disability under the ADA; however, employers do not have to tolerate poor work performance due to alcoholism. If a person with alcoholism is provided only one paid leave for treatment of the alcoholism, while persons with different diseases are provided multiple paid leave, then such a provision is a violation of the ADA.

The ADA does not protect an individual currently engaging in the illegal use of drugs. However, a person with a history of drug addiction who (1) has been successfully rehabilitated or is participating in a drug rehabilitation program and (2) is not engaging in the illegal use of drugs is protected if the person is a qualified individual with a disability. An individual who is erroneously regarded as being a drug addict is also protected. [28 CFR § 35.104, 131]

Communications

People who have disabilities that affect hearing, seeing, speaking, reading, writing or understanding may use different ways to communicate than people who do not. Governmental agencies are required to take steps to ensure that the agency's communications with people with disabilities are as effective as communications with others. [28 CFR § 35.160(a)(1)]

This effective communication requirement applies to all members of the public with disabilities, including job applicants, program participants, and even people who simply contact state or local government agencies seeking information about programs, services, events or activities. The requirement applies to all agencies and to all modes of communication including written, spoken, telecommunications, television and video. Specifically, where the governmental agency communicates by telephone with applicants and any other person, text phones (TTY's) or equally effective telecommunications systems are required to be used for individuals who are deaf, hard of hearing, or have speech impairments. [28 CFR § 35.161]

When the government uses an automated-attendant system, including, but not limited to, voice mail and messaging, or an interactive voice response system, for receiving and directing incoming telephone calls, that system must provide for real-time communication with individuals using auxiliary aids and services, including TTY's and all forms of FCC-approved telecommunications relay system, including Internet-based relay systems. [28 CFR § 35.161]

Under 28 CFR § 35.161, the ADA requires that all Public Safety Answering Points (PSAPs) provide direct and equal access to their services for people with disabilities who use text phones (TTYs). All basic emergency services are included in this requirement. Both primary and secondary PSAPs have the same responsibilities under the ADA. To be in compliance, every call-taking position within the PSAP must have its own TTY or TTY-compatible equipment.

Additionally, telephone emergency services, including 911 services, shall provide direct access to individuals who use telecommunication devices for the deaf (TDD's) or computer modems. [28 CFR § 35.162]

The governmental agency must provide equal access to the programs, services and activities available on the agency's website(s). This can include making websites accessible to people with disabilities, or providing an alternative format for people to access the information, programs and services available through the web. In order to aid development of a government website which is accessible, the web administrator can consult the Web Content Accessibility Guidelines, developed by the Web Content Accessibility Working Group, which is part of the World Wide Web Consortium Web Accessibility Initiative, and available at <http://www.w3.org/TR/WCAG20>.

When an auxiliary aid or service is requested, the Department must provide an opportunity for the requester to specify aids or services of their choice, and that choice must be given primary consideration. There are many types of auxiliary aids and services that may be used to provide effective communication for people with disabilities, but not all ways work for all people or even for people with the same type of disability. The law does not require the agency to provide every one of these aids and services, but it does require that each person who interacts with the agency receives effective communication. [28 CFR § 35.160]

Requirements for an ADA Coordinator

A Title II entity with more than 50 employees must designate an ADA Coordinator who coordinates agency efforts to comply with and carry out the responsibilities of the ADA. The coordinator provides a single point of contact for members of the public about ADA and the agency. In order to ensure that individuals can easily identify the ADA Coordinator, the governmental agency must provide the ADA Coordinator's name, office address, and telephone number to all interested individuals [28 CFR § 35.107].

The ADA Coordinator facilitates compliance with the ADA and provides expertise regarding the American Disability Act and ADA Standards. The ADA coordinator receives and investigates complaints related to discrimination on the basis of disability.

Under 28 CFR § 35.107, a grievance procedure is required for public entities of 50 or more employees. Title II entities are required to adopt and publish grievance procedures providing for prompt and equitable resolution of complaints alleging any action that would be prohibited by 28 CFR § 35.

New Construction and Alterations

A public Title II entity may not deny the benefits of its programs, activities, and services to persons with disabilities because its existing facilities are inaccessible. Thus, it is the general availability of a program to persons with disabilities that must be evaluated, not compliance with facility standards developed for new construction and alterations.

While state and local governments may wish to measure the accessibility of their existing buildings against the scoping and technical provisions in the 2010 Standards, program accessibility may be achieved without making every existing facility - or every part of an existing building - accessible. Alternatives to building retrofit can include the temporary relocation of an activity to an accessible facility or the delivery of the service or benefit by other means. In many cases, however, permanent construction that provides physical access may be the most efficient and economical approach to program access, particularly when life cycle costs are considered.

Although physical changes are required only when there is no other feasible way to make a program accessible, public entities are nevertheless required to give priority to methods that result in the most integrated setting appropriate. The program access obligation is limited: title II entities do not have to take actions that they can demonstrate would result in a fundamental alteration in the nature of a program or that would impose undue financial or administrative burdens.

In compliance with 28 CFR §35.151 (c), if new construction and alterations to a facility were begun prior to September 15, 2010, then the facility or portion of the facility that is affected by the alteration shall comply with the 1991 standards. If new construction and alterations to a facility were begun on or after September 15, 2010, and before March 15, 2012, then either the 1991 standards or the 2010 ADA Standards for Accessible Design are applicable. For all new construction or alterations begun on or after March 15, 2012, the 2010 ADA Standards for Accessible Design are applicable. New construction and alterations must fully comply with all applicable 2010 ADA Standards for Accessible Design if begun on or after March 15, 2012.

The DOJ definition of the commencement of construction is the establishment of a physical object, such as a foundation wall, rather than the groundbreaking first shovel and initial grading of the site.

Existing facilities (including all buildings, exterior facilities, and the on-site access to them) constructed prior to January 26, 1992, and not altered in any way since that date, are held to the lesser standard of complying, with the extent allowed by structural feasibility and the financial resources available, or when a reasonable accommodation can be made.

If the cost of providing a path of travel to an altered facility is more than 20% of the cost of the alteration to the primary function area, then the cost is disproportionate to the overall area and therefore not required. Costs that may be considered as part of the cost of providing an accessible path of travel may include: (1) the costs associated with providing an accessible entrance and an accessible route to the altered area, for example, the cost of widening doorways or installing ramps; (2) costs associated with making restrooms accessible, such as installing grab bars, enlarging toilet stalls, insulating pipes, or installing accessible faucet controls, if the restroom is not the primary function of the area (e.g. the restroom is not in a highway rest area); (3) costs associated with providing accessible telephones, such as relocating the telephone to an accessible height, installing amplification devices, or installing a text telephone (TTY); and (4) costs associated with relocating an inaccessible drinking fountain. [28 C.F.R. § 35.151(b)(4)(iii)]

When the cost of alterations necessary to make the path of travel to the altered area fully accessible is disproportionate to the cost of the overall alteration, the path shall be made accessible to the extent that it can without incurring disproportionate costs. In choosing which accessible elements to provide, priority should be given to those elements that will provide the greatest access, in the following order: (1) an accessible entrance; (2) an accessible route to the altered area; (3) at least one accessible restroom for each sex or a single unisex restroom; (4) accessible telephones; (5) accessible drinking fountains; and (6) when possible, additional accessible elements such as parking storage and alarms. [28 CFR § 35.151(b)(4)(iv)] A series of smaller alterations cannot be used to evade the requirement if the alterations are served by a single path of travel. [28 C.F.R. § 35.151(b)(4)(v)]

Safe Harbor

The 2010 ADA Standards for Accessible Design use the terms incremental change and supplemental change. Incremental changes are those elements which were requirements under the 1991 standards, but which were changed in some way under the 2010 standards. Supplemental changes are those regulations or regulatory areas which were not included in the 1991 standards, but are included in the 2010 standards.

“Safe harbor” is the term used in the 2010 ADA Standards to describe situations where the 2010 incremental changes to the ADA regulations are not required if alterations to the building or facility are not made. Specifically, “safe harbor” applies to a path of travel. “A ‘path of travel’ includes a continuous, unobstructed way of pedestrian passage by means of which the altered area may be approached, entered, and exited, and which connects the altered area with an exterior approach (including sidewalks, streets, and parking areas), an entrance to the facility and other parts of the facility. “[28 CFR § 35.151(b)(4)(ii)] “An accessible path of travel may consist of walks and sidewalks, curb ramps and other interior or exterior pedestrian ramps; clear floor paths through lobbies, corridors, rooms, and other improved areas; parking access aisles; elevators and lifts; or a combination of these elements. For the purposes of the section the term ‘path of travel’ also includes the restrooms, telephones and drinking fountains serving the altered area.” [28 C.F.R. § 35.151(b)(4)(ii)(B)]

Safe harbor applies only if a building or facility built after July 26, 1992 was compliant with the 1991 standards prior to the enforceable date of the 2010 regulations, which is March 15, 2012. "Safe harbor" is granted to facilities or buildings if and only if the facilities are fully in compliance with the 1991 standards prior to March 15, 2012. However, if alterations are made after March 15, 2012, the alteration of the building or facility must fully comply with the 2010 standards, and any other portions of the existing building or facility that are substantially affected by the alteration in terms of their use, must also comply with the 2010 standards. "Safe harbor" does not apply to areas of supplemental change. For instance, the 2010 standards include regulations for exercise equipment or exercise areas, play areas, recreational boating, mini-golf, swimming pools, bowling, and court sports, but those regulations are not governed by "safe harbor." Other supplemental changes not enumerated here are also not covered by "safe harbor". [28 C.F.R. § 35.151(b)(4)(ii)(c)]

For example, one of the regulated areas where "safe harbor" makes an impact is in a single occupant restroom. The 2010 ADA Standards for Accessible Design require a clear floor space next to the water closet, while the 1991 ADAAG allows the lavatory to overlap the clear space. The intent of the new provisions is to allow space for a side transfer to the water closet. The 2010 ADA Standards allow the door to swing into the bathroom as long as there is a clear floor space past the swing of the door, so that a person can enter the room, shut the door and then maneuver. The 1991 ADAAG does not allow the door swing and the clear floor space to overlap for any of the fixtures. While the 2010 standards do not allow clear space overlap in multi-stall bathrooms, overlap is allowed in single occupant bathrooms.

Undue Burden

A public entity must operate each service, program, or activity so that when viewed in its entirety, the service, program, or activity is readily accessible to and usable by individuals with disabilities. This does not necessarily require the public entity to make each of its facilities accessible to and usable by individuals with disabilities. Additionally, a public entity is not required to take any action that would threaten or destroy the historical significance of an historic property.

If the state or local government agency can demonstrate that an action would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens, then the decision must be made in a written statement describing the reason for the conclusion, and the decision must be made by the head of the government agency, or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity. The public entity has the burden of proof that compliance with 28 CFR § 35.151 would result in such alterations or burdens.

If an action would result in a fundamental alteration of the service, program, or activity or in undue financial and administrative burdens, the Title II entity shall take any other action to ensure that individuals with disabilities receive the benefits or services provided by the state or local government agency.

Self-Evaluation Requirements

A Self-Evaluation is a governmental organizations' evaluation of its current services, policies and practices, and all physical facilities. The Self Evaluation comprises three components: 1. Data gather/assessments/internal reviews, etc., 2. The Transition Plan, and 3. Action to make necessary modifications. A government entity is required to conduct a Self-Evaluation within one year of the effective date of 28 CFR § 35.105, the effective date being March 15, 2011. All governments were required to complete a Self-Evaluation of their facilities, programs, policies, and practices by January 26, 1993. The evaluation required by March 15, 2012 is required to cover any and all areas that were not covered under the previous Self-Evaluation, including any programs or facilities that were altered since the previous Self-Evaluation. If a previous self-evaluation was not conducted, then the Self-Evaluation required by March 15, 2012 must include all facilities, services, policies, and practices.

The Self-Evaluation identifies and corrects those policies and practices that are inconsistent with Title II's requirements. Self-Evaluations should consider all of a local government's programs, activities, and services, as well as the policies and practices that a governmental agency has put in place to implement its various programs and services. Remedial measures necessary to bring the programs, policies, and services into compliance with Title II should be specified -- including, but not limited to: (1) relocation of programs to accessible facilities; (2) offering programs in an alternative accessible manner; (3) structural changes to provide program access; (4) policy modifications to ensure nondiscrimination; and (5) auxiliary aids needed to provide effective communication. [28 CFR §§ 35.105, 35.150(d)] The Self-Evaluation process identifies those policies and practices that are inconsistent with the requirements of Title II of the ADA. As part of the Self-Evaluation, the governmental agency is required to:

- A. Identify all of its programs, activities, and services.
- B. Review all the policies and practices that govern the administration of the governmental agency's programs, activities, and services.
- C. Examine each program to determine whether any physical barriers to access exist, including whether individuals with mobility impairments are provided access to public meetings.
- D. Review its policies and practices to determine whether any have the effect of excluding or limiting the participation of individuals with disabilities in the governmental agency's programs, activities, or services. The Self-Evaluation should provide justification for any agency policy that creates a barrier for people with disabilities that will not be modified.
- E. Review its policies to assess whether communications with persons with disabilities are as effective as its communication with others.
- F. Review its policies for responding to requests for accommodations to ensure such requests are responded to expeditiously.
- G. Review its employment practices to assess whether they comply with other applicable nondiscrimination requirements, including Section 504 of the Rehabilitation Act and the ADA regulations issued by the Department of Justice.
- H. Review its building and construction policies to assess whether construction of each new facility or part of a facility, or alteration of existing facilities, conforms to the standards designated under the Title II regulations.
- I. Provide the opportunity to interested persons, including individuals with disabilities or organizations representing individuals with disabilities, to participate in the Self-Evaluation process by submitting comments.

In addition, a public entity that employs 50 or more persons shall for at least three years following completion of the Self-Evaluation maintain on file and make available for public inspection: (1) a list of the interested persons consulted; (2) a description of areas examined and any problems identified, and (3) a description of any modification made.

Transition Plan Requirements

If a state or local government that employs 50 or more persons decides to make structural changes to achieve program access, it must develop a transition plan that identifies those changes and sets a schedule for implementing them. Transition plans must be available to the public.

28 CFR §35.150 (d) Transition plan: (1) In the event that structural changes to facilities will be undertaken to achieve program accessibility, a public entity that employs 50 or more persons shall develop, within six months of the effective date of this part, a transition plan setting forth the steps necessary to complete such changes. A public entity shall provide an opportunity to interested persons, including individuals with disabilities or organizations representing individuals with disabilities, to participate in the development of the transition plan by submitting comments. A copy of the transition plan shall be made available for public inspection.

(2) If a public entity has responsibility or authority over streets, roads, or walkways, its transition plan shall include a schedule for providing curb ramps or other sloped areas where pedestrian walks cross curbs, giving priority to walkways serving entities covered by the Act, including State and local government offices and facilities, transportation, places of public accommodation, and employers, followed by walkways serving other areas.

(3) The plan shall, at a minimum -

(i) Identify physical obstacles in the public entity’s facilities that limit the accessibility of its programs or activities to individuals with disabilities;

(ii) Describe in detail the methods that will be used to make the facilities accessible;

(iii) Specify the schedule for taking the steps necessary to achieve compliance with this section and, if the time period of the transition plan is longer than one year, identify steps that will be taken during each year of the transition period; and

(iv) Indicate the official responsible for implementation of the plan.

28 CFR §35.151(b)(4) path of travel requirements apply only to alterations undertaken solely for purposes other than to meet program accessibility requirements of 28 CFR §35.150 provides additional guidance regarding the duty to provide accessible features in the event of disproportionality of the cost to make corrections to barriers with the overall project costs. In the event of disproportionality, 28 CFR §35.151 (b) (4) Path of Travel (iv) states that when the cost of alterations necessary to make the path of travel to the altered area fully accessible is disproportionate to the cost of the overall alteration, the path of travel shall be made accessible to the extent that it can be made accessible without incurring disproportionate costs. Additional guidance supplied in relation to choosing which accessible elements to provide, priority should be given to those elements that will provide the greatest access, in the following order—

Priority 1: An accessible entrance;

Priority 2: An accessible route to the altered area;

Priority 3: At least one accessible restroom for each sex or a single unisex restroom;

Priority 4: Accessible telephones

Priority 5: Accessible drinking fountains; and

Priority 6: When possible, additional accessible elements such as parking, storage, and alarms

These priorities are provided for guidance only. The individual Title II entity can develop its own priorities to provide reasonable accommodation.

APPENDIX B

ACCESSIBILITY SUMMARIES BY FACILITY

Barrier Summary Report

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA	Total
248010	Sonoma Valley Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	Picnic Table 1 (PT1)	California Accessibility Code	\$943
248015	Sonoma Valley Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	Parking Lot 1 Stall P1	California Accessibility Code	\$8,285
248016	Sonoma Valley Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	Parking Lot 1 Stall P2	California Accessibility Code	\$8,285
248017	Sonoma Valley Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	Parking Lot 1 Stall P1	California Accessibility Code	\$552
248018	Sonoma Valley Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: A warning curb is not provided on a walkway where the walkway edge is more than 4" above the adjacent surface.	Walkway 1 (W1)	California Accessibility Code	\$473
248019	Sonoma Valley Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	Picnic Table 2 (PT2)	California Accessibility Code	\$943
248883	Guerneville Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: A van space and adjacent van aisle are not provided.	Parking Lot 1	California Accessibility Code	\$1,105
248884	Guerneville Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	Curb Ramp 1 (CR1)	California Accessibility Code	\$884
248885	Guerneville Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	Curb Ramp 1 (CR1)	California Accessibility Code	\$2,301
248886	Guerneville Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp 1 (CR1)	ADA	\$1,695
248887	Guerneville Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Walkway 1 (W1)	California Accessibility Code	\$3,753
248888	Guerneville Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Stair 1 (ST1)	California Accessibility Code	\$4,716
248889	Guerneville Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	Walkway 2 (W2)	California Accessibility Code	\$7,506
248891	Guerneville Library	EXTERIOR	Exterior Access Route	Ramp	1	CALIFORNIA: The ramp has running slopes and/or rises in excess of 1:12.	Ramp 1 (R1)	California Accessibility Code	\$13,058
248892	Guerneville Library	EXTERIOR	Exterior Access Route	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	Ramp 1 (R1)	California Accessibility Code	\$7,288
248894	Guerneville Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking stall markings are not compliant.	Parking Lot 2 Stall P1 (P1)	California Accessibility Code	\$552
248895	Guerneville Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	Parking Lot 2 Stall P1 (P1)	California Accessibility Code	\$552
248896	Guerneville Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	Parking Lot 2 Stall P2 (P2)	California Accessibility Code	\$8,285
248897	Guerneville Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The car parking stall markings are not compliant.	Parking Lot 2 Stall P2 (P2)	California Accessibility Code	\$0
248898	Guerneville Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Parking Lot 2 Stall P2 (P2)	ADA	\$118
248899	Guerneville Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	The adjacent surfaces at transitions to adjoining walks, gutters and streets at the curb ramp are not at the same level.	Curb Ramp 2 (CR2)	ADA	\$2,301
248900	Guerneville Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	Entrance 2 (ENT2)	California Accessibility Code	\$2,301
248901	Guerneville Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	Entrance 3 (ENT3)	California Accessibility Code	\$0
248902	Guerneville Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	Entrance 3 (ENT3)	California Accessibility Code	\$2,301
248903	Guerneville Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Entrance 3 (ENT3)	California Accessibility Code	\$889
249219	Guerneville Library	EXTERIOR	Accessible Parking	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	Parking Lot 1	California Accessibility Code	\$368
249220	Guerneville Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Walkway 2 (W2)	California Accessibility Code	\$0

249139	Rincon Valley Library	Exterior	Accessible Parking	Parking Space-Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	Accessible Parking Space P1	California Accessibility Code	\$8,285
249140	Rincon Valley Library	Exterior	Accessible Parking	Parking Space-Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	Accessible Aisle serving P1 and P2	California Accessibility Code	\$6,575
249141	Rincon Valley Library	Exterior	Accessible Parking	Parking Space-Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	Accessible Parking Space P2	California Accessibility Code	\$8,285
249142	Rincon Valley Library	Exterior	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	Van Accessible Parking Space P3	California Accessibility Code	\$8,285
249143	Rincon Valley Library	Exterior	Accessible Parking	Parking Space-Van	1	CALIFORNIA: The van aisle markings are not compliant.	Accessible Aisle serving P3	California Accessibility Code	\$552
249145	Rincon Valley Library	Exterior	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	Curb Ramp CR1	California Accessibility Code	\$2,301
249146	Rincon Valley Library	Exterior	Exterior Access Route	Curb Ramp	1	The curb ramp surface has vertical height changes greater than 1/4" that are not ramped.	Curb Ramp CR1	ADA	\$0
249147	Rincon Valley Library	Exterior	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR2	ADA	\$2,301
249148	Rincon Valley Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Walkway from CR2 to CR3	California Accessibility Code	\$11,728
249149	Rincon Valley Library	Exterior	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR3	ADA	\$2,301
249150	Rincon Valley Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Walkway to Trash Enclosure	California Accessibility Code	\$14,465
249153	Rincon Valley Library	Exterior	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes. The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR4	California Accessibility Code	\$3,996
249154	Rincon Valley Library	Exterior	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes. The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR5	California Accessibility Code	\$3,996
249156	Rincon Valley Library	Exterior	Exterior Access Route	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	Ramp R1	California Accessibility Code	\$12,861
249157	Rincon Valley Library	Exterior	Exterior Access Route	Ramp	1	CALIFORNIA: The ramp run does not have edge protection or the edge protection is not compliant.	Ramp R1	California Accessibility Code	\$12,861
249158	Rincon Valley Library	Exterior	Exterior Access Route	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	Ramp R1	California Accessibility Code	\$9,576
249159	Rincon Valley Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Walkway from Montecito Blvd to Building Entrance	California Accessibility Code	\$10,425
249160	Rincon Valley Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Walkway from Montecito Blvd to Building Entrance	ADA	\$658
249213	Rincon Valley Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Courtyard	California Accessibility Code	\$7,819
249214	Rincon Valley Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	Courtyard	ADA	\$132
249215	Rincon Valley Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Courtyard	ADA	\$658
249216	Rincon Valley Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	The push side of the accessible door does not have the required maneuvering clearances.	Courtyard	ADA	\$1,644
250959	Rincon Valley Library	Exterior	Accessible Parking	Parking Space-Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	Accessible Parking Space P1 & P2	California Accessibility Code	\$552
247918	Petaluma Library	EXTERIOR	Accessible Parking	Exterior Accessible Route	1	An accessible passenger loading/unloading zone is not provided where a loading/unloading area is present.	Parking Lot 1	ADA	\$3,419
247919	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	The access aisle is less than 60" wide.	Parking Lot 1 Accessible Parking Stall P1	ADA	\$0

247920	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	Parking Lot 1 Accessible Parking Stall P1	California Accessibility Code	\$6,575
247921	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The car aisle markings are not compliant.	Parking Lot 1 Accessible Parking Stall P1	California Accessibility Code	\$1,105
247922	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The parking stall is less than the required minimum length of 216" (18').	Parking Lot 1 Accessible Parking Stall P1	California Accessibility Code	\$552
247923	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	Parking Lot 1 Accessible Parking Stall P1 & P3	California Accessibility Code	\$736
247924	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	Parking Lot 1 Accessible Parking Stall P2	California Accessibility Code	\$368
247925	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	Parking Lot 1 Accessible Parking Stall P1	California Accessibility Code	\$8,285
247926	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	Parking Lot 1 Accessible Parking Stall P1	California Accessibility Code	\$6,575
247927	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	Parking Lot 1 Accessible Parking Stall P2	California Accessibility Code	\$8,285
247928	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking aisle is less than 96" wide, where the van stall is less than 144" wide.	Parking Lot 1 Accessible Parking Stall P2	California Accessibility Code	\$0
247929	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	Parking Lot 1 Accessible Parking Stall P2	California Accessibility Code	\$6,575
247930	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	Parking Lot 1 Accessible Parking Stall P2	California Accessibility Code	\$552
247931	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The parking stall is less than the required minimum length of 216" (18').	Parking Lot 1 Accessible Parking Stall P3	California Accessibility Code	\$552
247932	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The parking stall is less than the required minimum length of 216" (18').	Parking Lot 1 Accessible Parking Stall P2	California Accessibility Code	\$552
247933	Petaluma Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The parallel curb ramp does not have a compliant detectable warning on the landing at the bottom of the curb ramp.	Curb Ramp CR1	California Accessibility Code	\$884
247934	Petaluma Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	The adjacent surfaces at transitions to adjoining walks, gutters and streets at the curb ramp are not at the same level.	Curb Ramp CR1	ADA	\$2,301
247935	Petaluma Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	Curb Ramp CR1	California Accessibility Code	\$2,301
247936	Petaluma Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The parallel curb ramp does not have a compliant turning space at the bottom of the curb ramp runs.	Curb Ramp CR1	California Accessibility Code	\$417
247938	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: A van space and adjacent van aisle are not provided.	Parking Lot 2	California Accessibility Code	\$1,105
247939	Petaluma Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The counter slopes of adjoining gutters and streets within 24" of the curb ramp are greater than 1:20 (5%).	Curb Ramp CR2	California Accessibility Code	\$2,301
247942	Petaluma Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	Main Entrance	California Accessibility Code	\$2,301
247945	Petaluma Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stair ST1	California Accessibility Code	\$93
247946	Petaluma Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Stair ST1	California Accessibility Code	\$1,286

247947	Petaluma Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	Reading Garden	California Accessibility Code	\$6,127
247948	Petaluma Library	EXTERIOR	Exterior Access Route	Ramp	1	CALIFORNIA: The ramp has running slopes and/or rises in excess of 1:12.	Ramp R1	California Accessibility Code	\$27,857
247949	Petaluma Library	EXTERIOR	Exterior Access Route	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	Ramp R1	California Accessibility Code	\$10,289
247950	Petaluma Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	Curb Ramp CR3	California Accessibility Code	\$884
247951	Petaluma Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The counter slopes of adjoining gutters and streets within 24" of the curb ramp are greater than 1:20 (5%).	Curb Ramp CR3	California Accessibility Code	\$2,301
247952	Petaluma Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp is non-compliant.	Curb Ramp CR3	California Accessibility Code	\$3,996
247953	Petaluma Library	EXTERIOR	Exterior Access Route	Ramp	1	CALIFORNIA: The ramp run does not have edge protection or the edge protection is not compliant.	Ramp R1	California Accessibility Code	\$0
247954	Petaluma Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	Staff Entrance	California Accessibility Code	\$189
247955	Petaluma Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	Staff Entrance	California Accessibility Code	\$2,301
247956	Petaluma Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	Staff Entrance	California Accessibility Code	\$481
248592	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	Parking Lot 2	California Accessibility Code	\$368
248523	Sebastopol Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stair 1 (ST1)	California Accessibility Code	\$278
248524	Sebastopol Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Stair 1 (ST1)	California Accessibility Code	\$5,144
248525	Sebastopol Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stair 2 (ST2)	California Accessibility Code	\$324
248526	Sebastopol Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Stair 2 (ST2)	California Accessibility Code	\$8,574
248527	Sebastopol Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stair 3 (ST3)	California Accessibility Code	\$324
248528	Sebastopol Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Stair 3 (ST3)	California Accessibility Code	\$5,144
248529	Sebastopol Library	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has cross slopes in excess of 1:48 (2.08%).	Ramp 1 (R1)	ADA	\$27,857
248530	Sebastopol Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	Main Entrance East	California Accessibility Code	\$1,644
248531	Sebastopol Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The power operated door is not compliant.	Main Entrance East	California Accessibility Code	\$3,419
248534	Sebastopol Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stair 4 (ST4)	California Accessibility Code	\$185
248537	Sebastopol Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The power operated door is not compliant.	Main Entrance West	California Accessibility Code	\$3,419
248539	Sebastopol Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Main Entrance Doors	California Accessibility Code	\$1,778
248613	Sebastopol Library	EXTERIOR	Exterior Access Route	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	Ramp 1 (R1)	California Accessibility Code	\$14,575
248614	Sebastopol Library	EXTERIOR	Exterior Access Route	Ramp	1	CALIFORNIA: The ramp run does not have edge protection or the edge protection is not compliant.	Ramp 1 (R1)	California Accessibility Code	\$6,859
248074	Rohnert Park-Cotati Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	Parking Lot 1 Accessible Parking Stall P3	California Accessibility Code	\$8,285

248075	Rohnert Park-Cotati Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	Parking Lot 1 Accessible Parking Stall P3	California Accessibility Code	\$6,575
248076	Rohnert Park-Cotati Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	Parking Lot 1 Accessible Parking Stall P5	California Accessibility Code	\$6,575
248077	Rohnert Park-Cotati Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	Parking Lot 1 Accessible Parking Stall P6	California Accessibility Code	\$8,285
248078	Rohnert Park-Cotati Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	Parking Lot 1 Accessible Parking Stall P1, P3, P5	California Accessibility Code	\$1,105
248079	Rohnert Park-Cotati Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	Parking Lot 1 Accessible Parking Stall P2, P4, P6	California Accessibility Code	\$1,105
248081	Rohnert Park-Cotati Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	Curb Ramp CR1	California Accessibility Code	\$884
248082	Rohnert Park-Cotati Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	Curb Ramp CR1	California Accessibility Code	\$2,301
248083	Rohnert Park-Cotati Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Walkway W1	California Accessibility Code	\$8,132
248084	Rohnert Park-Cotati Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Walkway W2	California Accessibility Code	\$8,132
248085	Rohnert Park-Cotati Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	Curb Ramp CR2	California Accessibility Code	\$884
248086	Rohnert Park-Cotati Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The hazardous vehicular area does not have a detectable warning or the existing detectable warning is not compliant.	Crosswalk CW1	California Accessibility Code	\$884
248087	Rohnert Park-Cotati Library	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	CALIFORNIA: The loading/unloading access aisle is not marked or the existing aisle marking is not compliant.	Main Entrance	California Accessibility Code	\$5,589
248088	Rohnert Park-Cotati Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	Main Entrance	California Accessibility Code	\$1,644
248089	Rohnert Park-Cotati Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The power operated door is not compliant.	Main Entrance	California Accessibility Code	\$3,419
248093	Rohnert Park-Cotati Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	Reading Grove	California Accessibility Code	\$1,131
248978	Healdsburg Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stair 1 (ST1)	California Accessibility Code	\$139
248979	Healdsburg Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Stair 1 (ST1)	California Accessibility Code	\$2,143
248980	Healdsburg Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The power operated door is not compliant.	Main Entrance	California Accessibility Code	\$3,419
248982	Healdsburg Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	Main Entrance	California Accessibility Code	\$1,644
248983	Healdsburg Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Walkway 1 (W1)	California Accessibility Code	\$2,815
248984	Healdsburg Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Walkway 2 (W2)	California Accessibility Code	\$1,277
248985	Healdsburg Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	Curb Ramp 1 (CR1)	California Accessibility Code	\$884
248986	Healdsburg Library	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp 1 (CR1)	ADA	\$1,695
248987	Healdsburg Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	Entrance 2 (ENT2)	California Accessibility Code	\$1,644
248988	Healdsburg Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The hazardous vehicular area does not have a detectable warning or the existing detectable warning is not compliant.	Parking Lot 1	California Accessibility Code	\$884
248991	Healdsburg Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	Parking Lot 1 Stall P1	California Accessibility Code	\$8,285

248992	Healdsburg Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: The car parking stall markings are not compliant.	Parking Lot 1 Stall P1	California Accessibility Code	\$0
248993	Healdsburg Library	EXTERIOR	Accessible Parking	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	Parking Lot 1 Stall P1	California Accessibility Code	\$368
248994	Healdsburg Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	Parking Lot 1 Stall P2	California Accessibility Code	\$6,575
248995	Healdsburg Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	Parking Lot 1 Stall P2	California Accessibility Code	\$0
248996	Healdsburg Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	Parking Lot 1 Stall P2	California Accessibility Code	\$8,285
248997	Healdsburg Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking stall markings are not compliant.	Parking Lot 1 Stall P2	California Accessibility Code	\$0
248998	Healdsburg Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	Parking Lot 1 Stall P2	California Accessibility Code	\$368
248999	Healdsburg Library	EXTERIOR	Exterior Access Route	Building Entrance - Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Entrance 3 (ENT3)	California Accessibility Code	\$889
249000	Healdsburg Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	Entrance 3 (ENT3)	California Accessibility Code	\$1,644
249001	Healdsburg Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	Walkway 3 (W3)	California Accessibility Code	\$2,502
249002	Healdsburg Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Walkway 3 (W3)	California Accessibility Code	\$0
249003	Healdsburg Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	Entrance 4 (ENT4)	California Accessibility Code	\$1,644
249004	Healdsburg Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	Entrance 5 (ENT5)	California Accessibility Code	\$0
249005	Healdsburg Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	Entrance 5 (ENT5)	California Accessibility Code	\$2,301
249006	Healdsburg Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The hazardous vehicular area does not have a detectable warning or the existing detectable warning is not compliant.	Entrance 5 (ENT5)	California Accessibility Code	\$884
248821	Windsor Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Site	ADA	\$9,904
248823	Windsor Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The power operated door is not compliant.	Main Entrance	California Accessibility Code	\$3,419
248851	Windsor Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Staff Entrance	California Accessibility Code	\$889
248858	Windsor Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	Community Room	California Accessibility Code	\$0
248859	Windsor Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Community Room	ADA	\$963
248860	Windsor Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Community Room	California Accessibility Code	\$1,778
249243	Northwest Santa Rosa Library	Exterior	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The parallel curb ramp is not compliant, or is required but not provided.	Curb Ramp CR1	California Accessibility Code	\$2,301
249245	Northwest Santa Rosa Library	Exterior	Accessible Parking	Parking Space - General	1	Accessible parking spaces are not at the nearest accessible entrance.	Parking Lot	ADA	\$552
249246	Northwest Santa Rosa Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	East Walkway from Guerneville Rd Building	ADA	\$261
249247	Northwest Santa Rosa Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	East Walkway from Guerneville Rd Building	ADA	\$658
249248	Northwest Santa Rosa Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	East Walkway from Guerneville Rd Building	California Accessibility Code	\$18,244
249249	Northwest Santa Rosa Library	Exterior	Exterior Access Route	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	Curb Ramp CR1	California Accessibility Code	\$884
249250	Northwest Santa Rosa Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The hazardous vehicular area does not have a detectable warning or the existing detectable warning is not compliant.	Walkway to Building	California Accessibility Code	\$39,766
249251	Northwest Santa Rosa Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The accessible route does not have 80" vertical clearance.	West Walkway from Guerneville Rd Building	California Accessibility Code	\$658

249252	Northwest Santa Rosa Library	Exterior	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	West Walkway from Guerneville Rd Building	ADA	\$130
249254	Northwest Santa Rosa Library	Exterior	Exterior Access Route	Reach Range	1	Clear space is not provided at the control or operating mechanism.	Walkway to Building	ADA	\$626
249256	Northwest Santa Rosa Library	Exterior	Entrance to Building	Building Entrance - Door	1	Clear space is not provided at the control or operating mechanism.	Building Entrance	ADA	\$313
249258	Northwest Santa Rosa Library	Exterior	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	Building Entrance	California Accessibility Code	\$0
249282	Northwest Santa Rosa Library	Exterior	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	Staff Entrance	California Accessibility Code	\$481
249283	Northwest Santa Rosa Library	Exterior	Entrance to Building	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Staff Entrance	ADA	\$0
249284	Northwest Santa Rosa Library	Exterior	Entrance to Building	Building Entrance - Door	1	The threshold at the accessible door is greater than 1/2" in height.	Staff Entrance	ADA	\$235
248942	Cloverdale Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: The van parking stall markings are not compliant.	Parking Lot 1 Stall P1	California Accessibility Code	\$552
248943	Cloverdale Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	Walkway 1 (W1)	California Accessibility Code	\$14,074
248944	Cloverdale Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The power operated door is not compliant.	Main Entrance	California Accessibility Code	\$3,419
248716	Central Library	EXTERIOR	Accessible Parking	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	Parking Lot 1 Stall P1	California Accessibility Code	\$368
248717	Central Library	EXTERIOR	Exterior Access Route	Ramp	1	CALIFORNIA: The exterior ramp railings do not extend 12" horizontally above the landing beyond the top and bottom of the ramp runs and in the same direction of the ramp run.	Ramp 1 (R1)	California Accessibility Code	\$214
248718	Central Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stair 1 (ST1)	California Accessibility Code	\$185
248719	Central Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The stair handrail extensions are not compliant.	Stair 1 (ST1)	California Accessibility Code	\$214
248720	Central Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stair 2 (ST2)	California Accessibility Code	\$648
248721	Central Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Stair 2 (ST2)	California Accessibility Code	\$3,001
248722	Central Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stair 3 (ST3)	California Accessibility Code	\$648
248723	Central Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Stair 3 (ST3)	California Accessibility Code	\$3,644
248725	Central Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stair 4 (ST4)	California Accessibility Code	\$185
248726	Central Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Stair 4 (ST4)	California Accessibility Code	\$2,143
248727	Central Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stair 5 (ST5)	California Accessibility Code	\$185
248728	Central Library	EXTERIOR	Exterior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Stair 5 (ST5)	California Accessibility Code	\$2,143
248729	Central Library	EXTERIOR	Exterior Access Route	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	Ramp 2 (R2)	California Accessibility Code	\$9,860
248730	Central Library	EXTERIOR	Exterior Access Route	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	Ramp 2 (R2)	California Accessibility Code	\$6,964
248731	Central Library	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp 2 (R2)	ADA	\$18,281
248732	Central Library	EXTERIOR	Exterior Access Route	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	Ramp 3 (R3)	California Accessibility Code	\$12,003

248782	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	Reading Garden	ADA	\$3,288
248784	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	Reading Garden	California Accessibility Code	\$0
248785	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Reading Garden	ADA	\$963
248786	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The threshold at the accessible door is greater than ½" in height. The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Children's Reading Garden	ADA	\$2,301
248787	Central Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	Children's Reading Garden	California Accessibility Code	\$834
248788	Central Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Walkway 1 (W1)	ADA	\$391
248789	Central Library	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Walkway 1 (W1)	ADA	\$209
248791	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	Ground Level Staff Entrance	California Accessibility Code	\$0
248792	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Ground Level Staff Entrance	ADA	\$481
248814	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	Lower Level Staff Entrances	California Accessibility Code	\$0
248815	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Lower Level Staff Entrances	ADA	\$1,444
248816	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The threshold at the accessible door is greater than ½" in height. The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Lower Level Staff Entrances	ADA	\$6,904
249013	Healdsburg Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The power operated door is not compliant.	Main Entrance Lobby	California Accessibility Code	\$6,838
249014	Healdsburg Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Community Room	ADA	\$0
249015	Healdsburg Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Community Room	ADA	\$481
249017	Healdsburg Library	INTERIOR	Common Areas	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Community Room	California Accessibility Code	\$1,156
249020	Healdsburg Library	INTERIOR	Kitchen	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Community Room Kitchenette	ADA	\$658
249047	Healdsburg Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Office	ADA	\$481
249048	Healdsburg Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Office	California Accessibility Code	\$385
249050	Healdsburg Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Reading Garden	ADA	\$0
249051	Healdsburg Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Reading Garden	ADA	\$481
249054	Healdsburg Library	INTERIOR	Employee Work Areas	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Staff Work Room	ADA	\$986
248909	Guerneville Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Community Room	ADA	\$0
248910	Guerneville Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Community Room	ADA	\$481
248912	Guerneville Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Throughout Building	California Accessibility Code	\$1,156
248917	Guerneville Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Community Room	California Accessibility Code	\$771
248919	Guerneville Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Book Return	California Accessibility Code	\$771
248921	Guerneville Library	INTERIOR	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Throughout Building	ADA	\$6,575

248923	Guerneville Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Reading Garden	ADA	\$0
248924	Guerneville Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Reading Garden	ADA	\$963
248926	Guerneville Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Office	California Accessibility Code	\$385
248852	Windsor Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Staff Work Room	ADA	\$482
248853	Windsor Library	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Staff Work Room	ADA	\$0
248855	Windsor Library	INTERIOR	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Library Stack Area	ADA	\$1,315
248861	Windsor Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Community Room	ADA	\$0
248862	Windsor Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Community Room	ADA	\$963
248949	Cloverdale Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Throughout Building	California Accessibility Code	\$3,468
248951	Cloverdale Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The power operated door is not compliant.	Main Entrance Vestibule	California Accessibility Code	\$6,838
248952	Cloverdale Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Book Return	California Accessibility Code	\$385
248958	Cloverdale Library	INTERIOR	Restroom	Restroom/Bathroom - Door	1	CALIFORNIA: The power operated door is not compliant.	Men's & Women's Restroom	California Accessibility Code	\$6,838
248966	Cloverdale Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Reading Garden	ADA	\$963
248967	Cloverdale Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Reading Garden	ADA	\$0
248974	Cloverdale Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Staff Work Room	ADA	\$481
248975	Cloverdale Library	INTERIOR	Interior Access Route	Door	1	Double-leaf doors are used and neither side is compliant.	Community Room Kitchenette	ADA	\$3,419
248547	Sebastopol Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Community Room & Breakroom	ADA	\$963
248548	Sebastopol Library	INTERIOR	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Community Room	ADA	\$3,945
248549	Sebastopol Library	INTERIOR	Interior Access Route	Door	1	The door has less than 32" clear width.	Community Room Kitchenette	ADA	\$3,419
248550	Sebastopol Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Community Room Kitchenette	California Accessibility Code	\$385
248559	Sebastopol Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Work Room & Breakroom	ADA	\$963
249267	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Lavatory	1	The interior accessible route has non-compliant slopes.	Men's/ Women's Restroom RR1/RR2	ADA	\$2,243
249275	Northwest Santa Rosa Library	Interior	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Main Library	ADA	\$1,315
249277	Northwest Santa Rosa Library	Interior	Interior Access Route	Interior Access Route	1	CALIFORNIA: The width of the aisle is not compliant.	Main Library	California Accessibility Code	\$263
249280	Northwest Santa Rosa Library	Interior	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Main Library	ADA	\$3,829
249281	Northwest Santa Rosa Library	Interior	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Librarian Office/ Staff Area	ADA	\$263
249292	Northwest Santa Rosa Library	Interior	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Break Room	ADA	\$132
249293	Northwest Santa Rosa Library	Interior	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Break Room	ADA	\$658
249295	Northwest Santa Rosa Library	Interior	Interior Access Route	Controls And Dispensers	1	Clear space is not provided at the control or operating mechanism.	Break Room	ADA	\$263

249297	Northwest Santa Rosa Library	Interior	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Break Room	ADA	\$658
248735	Central Library	INTERIOR	Interior Access Route	Stairs	1	CALIFORNIA: Treads, including top and bottom treads, of the interior stair flight do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Interior Staff Stair from Upper Level to Ground Level	California Accessibility Code	\$46
248736	Central Library	INTERIOR	Interior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Interior Staff Stair from Upper Level to Ground Level	California Accessibility Code	\$8,574
248737	Central Library	INTERIOR	Interior Access Route	Stairs	1	CALIFORNIA: Treads, including top and bottom treads, of the interior stair flight do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Interior Public Stair	California Accessibility Code	\$185
248738	Central Library	INTERIOR	Interior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Interior Public Stair	California Accessibility Code	\$12,003
248739	Central Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Throughout Building	California Accessibility Code	\$12,329
248745	Central Library	INTERIOR	Interior Access Route	Stairs	1	CALIFORNIA: Treads, including top and bottom treads, of the interior stair flight do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	North Stairs to Lower Level	California Accessibility Code	\$93
248746	Central Library	INTERIOR	Interior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	North Stairs to Lower Level	California Accessibility Code	\$9,002
248747	Central Library	INTERIOR	Interior Access Route	Stairs	1	CALIFORNIA: Treads, including top and bottom treads, of the interior stair flight do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	South Stairs to Lower Level	California Accessibility Code	\$93
248748	Central Library	INTERIOR	Interior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	South Stairs to Lower Level	California Accessibility Code	\$9,002
248761	Central Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The power operated door is not compliant.	Ground Floor Restrooms	California Accessibility Code	\$6,838
248770	Central Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Community Room	ADA	\$0
248771	Central Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Community Room	ADA	\$963
248772	Central Library	INTERIOR	Interior Access Route	Door	1	Double-leaf doors are used and neither side is compliant.	Community Room	ADA	\$3,419
248773	Central Library	INTERIOR	Interior Access Route	Door	1	The door has less than 32" clear width.	Community Room Kitchenette	ADA	\$3,419
248807	Central Library	INTERIOR	Interior Access Route	Door	1	The space between two doors in a series is less than 48" clear with doors open 90 degrees.	Staff Women's Restroom	ADA	\$1,420
249119	Central Library	INTERIOR	Interior Access Route	Door	1	The space between two doors in a series is less than 48" clear with doors open 90 degrees.	Ground Floor Staff Restrooms	ADA	\$2,840
249138	Central Library	INTERIOR	Interior Access Route	Door	1	The space between two doors in a series is less than 48" clear with doors open 90 degrees.	Staff Women's & Men's Restroom	ADA	\$2,840
248096	Rohnert Park-Cotati Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Throughout Building	ADA	\$6,257
248097	Rohnert Park-Cotati Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Throughout Building	ADA	\$0
248104	Rohnert Park-Cotati Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The power operated door is not compliant.	Men's & Women's Restroom	California Accessibility Code	\$6,838
248608	Rohnert Park-Cotati Library	INTERIOR	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Community Room Kitchen	ADA	\$658
248026	Sonoma Valley Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Throughout Building	ADA	\$1,444
248034	Sonoma Valley Library	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Library Circulation	ADA	\$957
247965	Petaluma Library	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Staff Breakroom	ADA	\$329
247966	Petaluma Library	INTERIOR	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Throughout Building	ADA	\$7,890

247968	Petaluma Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	Throughout Building	California Accessibility Code	\$3,468
247969	Petaluma Library	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Community Room	ADA	\$481
247970	Petaluma Library	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Community Room	ADA	\$481
247974	Petaluma Library	INTERIOR	Interior Access Route	Door	1	CALIFORNIA: The power operated door is not compliant.	Main Entrance Vestibule	California Accessibility Code	\$6,838
248005	Petaluma Library	INTERIOR	Interior Access Route	Stairs	1	CALIFORNIA: Treads, including top and bottom treads, of the interior stair flight do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	Stairs to 2nd Floor	California Accessibility Code	\$185
248006	Petaluma Library	INTERIOR	Interior Access Route	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	Stairs to 2nd Floor	California Accessibility Code	\$10,289
248008	Petaluma Library	INTERIOR	Interior Access Route	Head Room	1	The height of the interior accessible route is less than 80" AFF.	2nd Floor	ADA	\$957
249169	Rincon Valley Library	Interior	Restroom	Door	1	CALIFORNIA: The power operated door is not compliant.	Men's and Women's Restroom RR1/RR2	California Accessibility Code	\$6,838
249173	Rincon Valley Library	Interior	Restroom	Controls And Dispensers	1	The interior accessible route has non-compliant slopes.	Men's Restroom RR1	ADA	\$1,121
249184	Rincon Valley Library	Interior	Interior Access Route	Interior Access Route	1	CALIFORNIA: The width of the aisle is not compliant.	Children's Area	California Accessibility Code	\$395
249185	Rincon Valley Library	Interior	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Staff Office	ADA	\$132
249186	Rincon Valley Library	Interior	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	North Staff Area	ADA	\$1,644
249188	Rincon Valley Library	Interior	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	North Staff Area	ADA	\$963
249189	Rincon Valley Library	Interior	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	North Staff Area	ADA	\$0
249191	Rincon Valley Library	Interior	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	North Staff Area	ADA	\$957
249192	Rincon Valley Library	Interior	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	North Staff Area	ADA	\$132
249194	Rincon Valley Library	Interior	Entrance to Building	Building Entrance-Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	North Staff Area	California Accessibility Code	\$2,301
249207	Rincon Valley Library	Interior	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	South Staff Offices	ADA	\$1,444
249208	Rincon Valley Library	Interior	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	South Staff Offices	ADA	\$0
249217	Rincon Valley Library	Interior	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Teen Fiction	ADA	\$957
248013	Sonoma Valley Library	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Main Entrance	ADA	\$329
248890	Guerneville Library	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Main Entrance	ADA	\$1,578
249155	Rincon Valley Library	Exterior	Exterior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	North Book Returns	ADA	\$658
249161	Rincon Valley Library	Exterior	Exterior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	South Book Returns	ADA	\$658
249162	Rincon Valley Library	Exterior	Exterior Access Route	Reach Range	2	Clear ground space is not provided at the operable part.	South Book Returns	ADA	\$313
247943	Petaluma Library	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Main Entrance	ADA	\$329
248535	Sebastopol Library	EXTERIOR	Exterior Access Route	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	Stair 4 (ST4)	California Accessibility Code	\$857
248536	Sebastopol Library	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Main Entrance West	ADA	\$329

248091	Rohnert Park-Cotati Library	EXTERIOR	Exterior Access Route	Reach Range	2	Operable parts or items requiring an obstructed forward reach motion are higher than 48" maximum height where the depth of the obstruction is 20" maximum, or greater than 44" maximum height where the depth of the obstruction is 20" to 25" maximum, or lower than minimum 15" height above finish floor.	Main Entrance	ADA	\$1,315
248131	Rohnert Park-Cotati Library	EXTERIOR	Site Furnishings	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	Staff Patio	State of California	\$1,044
248981	Healdsburg Library	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Main Entrance	ADA	\$1,578
248822	Windsor Library	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Main Entrance	ADA	\$1,578
249253	Northwest Santa Rosa Library	Exterior	Exterior Access Route	Reach Range	2	Operable parts or items requiring an obstructed side reach motion are higher than 48" maximum where the obstruction depth is 10" maximum, or higher than 46" maximum where the obstruction depth is between 10" and 24" and/or lower than 15" minimum height above finish floor.	Walkway to Building	ADA	\$1,315
249257	Northwest Santa Rosa Library	Exterior	Entrance to Building	Building Entrance - Door	2	The provided signage does not have color contrast and a non-glare finish.	Building Entrance	ADA	\$72
249285	Northwest Santa Rosa Library	Exterior	Entrance to Building	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	Staff Entrance	ADA	\$526
248945	Cloverdale Library	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Main Entrance	ADA	\$1,578
248781	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	Reading Garden, Community Room, Children's Library	ADA	\$3,682
248790	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	Ground Level Staff Entrance	ADA	\$526
248813	Central Library	EXTERIOR	Entrance to Building	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	Lower Level Staff Entrances	ADA	\$1,578
249007	Healdsburg Library	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Throughout Building	ADA	\$506
249008	Healdsburg Library	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Throughout Building	ADA	\$434
249009	Healdsburg Library	INTERIOR	Interior Access Route	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	Main Entrance Lobby	ADA	\$1,578
249010	Healdsburg Library	INTERIOR	Detention/Correctional Facilities	Detention Cell	2	None of the telephones are TTY enabled.	Main Entrance Lobby	ADA	\$1,973
249018	Healdsburg Library	INTERIOR	Common Areas	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Community Room	ADA	\$1,315
249019	Healdsburg Library	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Community Room Kitchenette	ADA	\$947
249026	Healdsburg Library	INTERIOR	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Men's & Women's Restroom	ADA	\$658
249028	Healdsburg Library	INTERIOR	Restroom	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Men's & Women's Restroom	ADA	\$197
249042	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom	2	CALIFORNIA: The baby changing table is not compliant.	Men's & Women's Restroom	State of California	\$2,088
249043	Healdsburg Library	INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Library Circulation	ADA	\$2,373
249044	Healdsburg Library	INTERIOR	Common Areas	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Throughout Building	ADA	\$3,156
249045	Healdsburg Library	INTERIOR	Common Areas	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Throughout Building	ADA	\$1,315
249046	Healdsburg Library	INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Library Reference	ADA	\$2,373
249049	Healdsburg Library	INTERIOR	Common Areas	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Information Center	ADA	\$947
249052	Healdsburg Library	INTERIOR	Common Areas	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	Reading Garden	State of California	\$1,044

249053	Healdsburg Library	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Staff Work Room	ADA	\$3,419
249055	Healdsburg Library	INTERIOR	Employee Work Areas	Reach Range	2	At least one each of shelves, clothes rod, drawer, hook, closets or cabinets are not within reach range.	Staff Work Room	ADA	\$263
249059	Healdsburg Library	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Staff Breakroom Kitchen	ADA	\$947
248905	Guerneville Library	INTERIOR	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Men's & Women's Restroom	ADA	\$658
248913	Guerneville Library	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Throughout Building	ADA	\$289
248914	Guerneville Library	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Throughout Building	ADA	\$651
248915	Guerneville Library	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Staff Work Room	ADA	\$3,419
248916	Guerneville Library	INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Community Room Kitchenette	ADA	\$947
248918	Guerneville Library	INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Library Circulation	ADA	\$2,373
248920	Guerneville Library	INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Library Reference	ADA	\$2,373
248922	Guerneville Library	INTERIOR	Interior Access Route	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	Office	ADA	\$592
248927	Guerneville Library	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Staff Breakroom Kitchen	ADA	\$947
249221	Guerneville Library	INTERIOR	Interior Access Route	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	Reading Garden	ADA	\$1,184
248824	Windsor Library	INTERIOR	Interior Access Route	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	Main Entrance Lobby	State of California	\$3,132
248836	Windsor Library	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Throughout Building	ADA	\$506
248837	Windsor Library	INTERIOR	Interior Access Route	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	Throughout Building	ADA	\$796
248838	Windsor Library	INTERIOR	Kitchen	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Staff Breakroom Kitchen	ADA	\$1,973
248839	Windsor Library	INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Staff Breakroom Kitchen	ADA	\$947
248854	Windsor Library	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Library Stack Area	ADA	\$3,156
248856	Windsor Library	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Library Stack Area	ADA	\$329
249230	Windsor Library	INTERIOR	Detention/Correctional Facilities	Detention Cell	2	None of the telephones available are TTY enabled.	Main Entrance Lobby	ADA	\$1,973
248946	Cloverdale Library	INTERIOR	Interior Access Route	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	Throughout Building	ADA	\$12,624
248947	Cloverdale Library	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Throughout Building	ADA	\$289
248948	Cloverdale Library	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Throughout Building	ADA	\$434
248953	Cloverdale Library	INTERIOR	Common Areas	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Throughout Building	ADA	\$3,156
248954	Cloverdale Library	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Throughout Building	ADA	\$1,184
248957	Cloverdale Library	INTERIOR	Common Areas	Assembly Area	2	The assistive listening device is not compliant or is not provided.	Community Room	ADA	\$1,315
248971	Cloverdale Library	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Staff Break Room Kitchen	ADA	\$947
248976	Cloverdale Library	INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Community Room Kitchenette	ADA	\$947

248551	Sebastopol Library	INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Community Room Kitchenette	ADA	\$2,840
248553	Sebastopol Library	INTERIOR	Common Areas	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Interior Book Return	ADA	\$329
248554	Sebastopol Library	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Throughout Building	ADA	\$506
248555	Sebastopol Library	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Community Room	ADA	\$217
248556	Sebastopol Library	INTERIOR	Interior Access Route	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	Community Room & Breakroom	ADA	\$145
248557	Sebastopol Library	INTERIOR	Common Areas	Controls And Dispensers	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Library Circulation	ADA	\$0
248560	Sebastopol Library	INTERIOR	Kitchen	Kitchen	2	Less than minimum one of each type of operable part is within reach range.	Staff Breakroom Kitchen	ADA	\$329
248561	Sebastopol Library	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Staff Kitchen Storage	ADA	\$72
248572	Sebastopol Library	INTERIOR	Common Areas	Controls And Dispensers	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Staff Work Room	ADA	\$1,315
249259	Northwest Santa Rosa Library	Interior	Interior Access Route	Signage	2	Means of egress signage does not have tactile lettering.	Building Entrance	ADA	\$72
249262	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	Men's/ Women's Restroom RR1/RR2	ADA	\$1,052
249264	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Lavatory	2	CALIFORNIA: The baby changing table is not compliant.	Men's/ Women's Restroom RR1/RR2	State of California	\$2,088
249266	Northwest Santa Rosa Library	Interior	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Men's/ Women's Restroom RR1/RR2	ADA	\$1,578
249276	Northwest Santa Rosa Library	Interior	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Main Library	ADA	\$145
249278	Northwest Santa Rosa Library	Interior	Interior Access Route	Dining And Work Surface	2	Work Surfaces for Children between ages 5 and 12: Minimum 5% of the work surface is not between 26" minimum and 30" maximum height, with knee and toe clearance for children at 24" minimum above floor or ground level.	Main Library	ADA	\$1,315
249279	Northwest Santa Rosa Library	Interior	Interior Access Route	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	Main Library	State of California	\$1,044
249287	Northwest Santa Rosa Library	Interior	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Unisex Restroom RR3	ADA	\$1,052
249294	Northwest Santa Rosa Library	Interior	Interior Access Route	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	Break Room	State of California	\$1,315
249296	Northwest Santa Rosa Library	Interior	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Break Room	ADA	\$132
249298	Northwest Santa Rosa Library	Interior	Interior Access Route	Operable Part	2	Clear floor space is not provided at the operable part.	Break Room	ADA	\$132
248740	Central Library	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Throughout Building	ADA	\$5,720
248744	Central Library	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Throughout Building	ADA	\$796
248752	Central Library	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Ground Floor Children's Library	ADA	\$1,578
248762	Central Library	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Throughout Building	ADA	\$2,748
248763	Central Library	INTERIOR	Restroom	Restroom/Bathroom	2	CALIFORNIA: The baby changing table is not compliant.	Ground Floor Restrooms	State of California	\$2,088
248768	Central Library	INTERIOR	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Ground Floor Restrooms	ADA	\$395
248774	Central Library	INTERIOR	Kitchen	Kitchen	2	The accessible route in the U-shaped kitchen is less than 60" wide.	Community Room Kitchenette	ADA	\$7,627
248775	Central Library	INTERIOR	Kitchen	Sink	2	The accessible sink does not have push/lever hardware.	Community Room Kitchenette	ADA	\$730
248776	Central Library	INTERIOR	Kitchen	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Community Room Kitchenette	ADA	\$947

248778	Central Library	INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Library Circulation	ADA	\$2,373
248779	Central Library	INTERIOR	Common Areas	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Ground Floor	ADA	\$1,578
248780	Central Library	INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Library Reference	ADA	\$2,373
248793	Central Library	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Staff Kitchen	ADA	\$947
248804	Central Library	INTERIOR	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Staff Women's & Men's Restroom	ADA	\$395
248812	Central Library	INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Lower Level	ADA	\$947
248817	Central Library	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Throughout Building	ADA	\$27,352
248098	Rohnert Park-Cotati Library	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Throughout Building	ADA	\$579
248099	Rohnert Park-Cotati Library	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Throughout Building	ADA	\$27,352
248102	Rohnert Park-Cotati Library	INTERIOR	Kitchen	Dispenser	2	Items requiring a reach motion, but do not have an operable part, are not within compliant reach ranges.	Community Room Kitchen	ADA	\$197
248111	Rohnert Park-Cotati Library	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Library Circulation	ADA	\$3,156
248119	Rohnert Park-Cotati Library	INTERIOR	Restroom	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Family Restroom	ADA	\$395
248128	Rohnert Park-Cotati Library	INTERIOR	Kitchen	Kitchen	2	Less than minimum one of each type of operable part is within reach range.	Staff Kitchen	ADA	\$658
248130	Rohnert Park-Cotati Library	INTERIOR	Employee Work Areas	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Staff Breakroom	ADA	\$658
248132	Rohnert Park-Cotati Library	INTERIOR	Employee Work Areas	Reach Range	2	At least one each of shelves, clothes rod, drawer, hook, closets or cabinets are not within reach range.	Staff Breakroom	ADA	\$197
248133	Rohnert Park-Cotati Library	INTERIOR	Common Areas	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	Staff Breakroom	State of California	\$1,044
248027	Sonoma Valley Library	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Main Entrance Vestibule	ADA	\$72
248028	Sonoma Valley Library	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Library Circulation	ADA	\$4,734
248029	Sonoma Valley Library	INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Library Circulation	ADA	\$2,373
248599	Sonoma Valley Library	INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Room #113 Kitchen	ADA	\$947
247957	Petaluma Library	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Throughout Building	ADA	\$506
247958	Petaluma Library	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Staff Entrance	ADA	\$658
247959	Petaluma Library	INTERIOR	Interior Access Route	Operable Part	2	Clear floor space is not provided at the operable part.	Staff Entrance	ADA	\$33
247960	Petaluma Library	INTERIOR	Common Areas	Reach Range	2	At least one each of shelves, clothes rod, drawer, hook, closets or cabinets are not within reach range.	Staff Entrance Corridor	ADA	\$197
247964	Petaluma Library	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Staff Breakroom	ADA	\$395
247967	Petaluma Library	INTERIOR	Interior Access Route	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	Throughout Building	ADA	\$579
247973	Petaluma Library	INTERIOR	Interior Access Route	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	Main Entrance Vestibule	ADA	\$3,156
247979	Petaluma Library	INTERIOR	Common Areas	Assembly Area	2	The assistive listening device is not compliant or is not provided.	Community Room	ADA	\$3,288
247980	Petaluma Library	INTERIOR	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Men's & Women's Restroom	ADA	\$1,841

247984	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom	2	CALIFORNIA: The baby changing table is not compliant.	Men's & Women's Restroom	State of California	\$2,088
247988	Petaluma Library	INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Library Circulation	ADA	\$2,373
247989	Petaluma Library	INTERIOR	Common Areas	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Library Circulation	ADA	\$3,156
247990	Petaluma Library	INTERIOR	Common Areas	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	Library Information Technology	State of California	\$197
247991	Petaluma Library	INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Library Reference	ADA	\$2,373
248594	Petaluma Library	INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Staff Breakroom	ADA	\$947
251812	Petaluma Library	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Staff Breakroom	ADA	\$658
249164	Rincon Valley Library	Interior	Interior Access Route	Signage	2	Means of egress signage does not have tactile lettering.	Exit Signs	ADA	\$723
249165	Rincon Valley Library	Interior	Interior Access Route	Operable Part	2	Clear floor space is not provided at the operable part.	Main Lobby	ADA	\$132
249166	Rincon Valley Library	Interior	Interior Access Route	Fire Alarm-Smoke Detection	2	The visual alarm system does not have compliant visual alarm appliances.	Main Lobby	ADA	\$3,945
249170	Rincon Valley Library	Interior	Restroom	Restroom/Bathroom - Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	Men's and Women's Restroom RR1/RR2	ADA	\$1,052
249171	Rincon Valley Library	Interior	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Men's and Women's Restroom RR1/RR2	ADA	\$3,288
249177	Rincon Valley Library	Interior	Restroom	Restroom/Bathroom - Door	2	CALIFORNIA: The baby changing table is not compliant.	Men's and Women's Restroom RR1/RR2	State of California	\$2,088
249181	Rincon Valley Library	Interior	Interior Access Route	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	Reading Room	State of California	\$1,315
249182	Rincon Valley Library	Interior	Interior Access Route	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	Reading Room	State of California	\$1,315
249183	Rincon Valley Library	Interior	Interior Access Route	Dining And Work Surface	2	Work Surfaces for Children between ages 5 and 12: Minimum 5% of the work surface is not between 26" minimum and 30" maximum height, with knee and toe clearance for children at 24" minimum above floor or ground level.	Children's Area	ADA	\$2,630
249187	Rincon Valley Library	Interior	Interior Access Route	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	North Staff Area	ADA	\$526
249190	Rincon Valley Library	Interior	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	North Staff Area	ADA	\$1,315
249193	Rincon Valley Library	Interior	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	North Staff Area	ADA	\$3,419
249195	Rincon Valley Library	Interior	Interior Access Route	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	North Staff Area	State of California	\$1,315
249197	Rincon Valley Library	Interior	Interior Access Route	Sink	2	Sinks do not have knee and/or toe clearance.	North Staff Area	ADA	\$2,612
249198	Rincon Valley Library	Interior	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	North Staff Area	ADA	\$658
249206	Rincon Valley Library	Interior	Interior Access Route	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	South Staff Offices	ADA	\$1,578
249209	Rincon Valley Library	Interior	Interior Access Route	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	South Staff Offices	State of California	\$1,315
249210	Rincon Valley Library	Interior	Interior Access Route	Appliance	2	Clear floor space at all sinks, works surfaces, operable parts and appliances is not provided.	Kitchen	ADA	\$132
248011	Sonoma Valley Library	EXTERIOR	Site Furnishings	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	Picnic Table 1 (PT1)	California Accessibility Code	\$1,710
248020	Sonoma Valley Library	EXTERIOR	Site Furnishings	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	Picnic Table 2 (PT2)	California Accessibility Code	\$1,710
247944	Petaluma Library	EXTERIOR	Exterior Access Route	Clear Space	3	Clear space is not provided at the operable part.	Main Entrance	ADA	\$313

248533	Sebastopol Library	EXTERIOR	Exterior Access Route	Clear Space	3	Clear space is not provided at the operable part.	Main Entrance East	ADA	\$313
248538	Sebastopol Library	EXTERIOR	Exterior Access Route	Clear Space	3	Clear space is not provided at the operable part.	Main Entrance West	ADA	\$164
248090	Rohnert Park-Cotati Library	EXTERIOR	Exterior Access Route	Clear Space	3	Clear space is not provided at the operable part.	Main Entrance	ADA	\$626
248094	Rohnert Park-Cotati Library	EXTERIOR	Site Furnishings	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	Reading Grove	California Accessibility Code	\$1,710
249012	Healdsburg Library	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	Main Entrance Lobby	California Accessibility Code	\$7,152
249016	Healdsburg Library	INTERIOR	Common Areas	Assembly Area	3	Assistive listening signage is not compliant or is not provided.	Community Room	ADA	\$72
249021	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	Men's & Women's Restroom	ADA	\$0
249022	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Men's & Women's Restroom	ADA	\$963
249023	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Men's & Women's Restroom	ADA	\$3,288
249024	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	Men's & Women's Restroom	California Accessibility Code	\$1,894
249025	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Men's & Women's Restroom	ADA	\$526
249027	Healdsburg Library	INTERIOR	Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	Men's & Women's Restroom	California Accessibility Code	\$395
249029	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Men's & Women's Restroom	ADA	\$771
249030	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Men's & Women's Restroom	ADA	\$771
249031	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	Men's & Women's Restroom	California Accessibility Code	\$2,893
249032	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Men's & Women's Restroom	ADA	\$934
249033	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	Men's & Women's Restroom	California Accessibility Code	\$3,598
249034	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Men's & Women's Restroom	ADA	\$1,657
249035	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	Men's & Women's Restroom	California Accessibility Code	\$0
249036	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Men's & Women's Restroom	ADA	\$934
249037	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	Men's Restroom	ADA	\$1,230
249038	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48".	Men's Restroom	ADA	\$329
249039	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	Men's & Women's Restroom	ADA	\$302
249041	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	Women's Restroom	California Accessibility Code	\$368
249056	Healdsburg Library	INTERIOR	Employee Work Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Staff Work Room	ADA	\$434
249057	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Staff Unisex Restroom	ADA	\$15,780
249058	Healdsburg Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width.	Staff Unisex Restroom	ADA	\$1,478
248906	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Men's Restroom	ADA	\$467
248907	Guerneville Library	INTERIOR	Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	Women's Restroom	California Accessibility Code	\$158

248908	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Women's Restroom	ADA	\$467
248911	Guerneville Library	INTERIOR	Common Areas	Assembly Area	3	Assistive listening signage is not compliant or is not provided.	Community Room	ADA	\$72
248925	Guerneville Library	INTERIOR	Common Areas	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	Reading Garden	California Accessibility Code	\$1,710
248929	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	Staff Unisex Restroom	California Accessibility Code	\$385
248930	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	Staff Unisex Restroom	California Accessibility Code	\$947
248931	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	Staff Unisex Restroom	ADA	\$85
248932	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Staff Unisex Restroom	ADA	\$828
248933	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Staff Unisex Restroom	ADA	\$412
248934	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The grab bars at the water closet are not compliant.	Staff Unisex Restroom	ADA	\$934
248935	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	Staff Unisex Restroom	California Accessibility Code	\$1,799
248936	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	Staff Unisex Restroom	California Accessibility Code	\$368
248937	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Signage	3	The provided signage is not mounted at the latch side of the door or at a compliant height.	Staff Unisex Restroom	ADA	\$72
248938	Guerneville Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	Staff Unisex Restroom	California Accessibility Code	\$1,447
248825	Windsor Library	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	Main Entrance Lobby	California Accessibility Code	\$7,152
248826	Windsor Library	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	Main Entrance Lobby	California Accessibility Code	\$7,152
248827	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Men's & Women's Restroom	ADA	\$771
248828	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Men's & Women's Restroom	ADA	\$771
248829	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Men's Restroom	ADA	\$412
248830	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Men's & Women's Restroom	ADA	\$934
248831	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	Men's & Women's Restroom	ADA	\$302
248833	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	Women's Restroom	California Accessibility Code	\$947
248834	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	Men's & Women's Restroom	ADA	\$0
248835	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Men's & Women's Restroom	ADA	\$963
248840	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	Staff Unisex Restroom	California Accessibility Code	\$145
248841	Windsor Library	INTERIOR	Employee Work Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Staff Work Room	ADA	\$434
248842	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The push side of the door does not have the required maneuvering clearances.	Staff Unisex Restroom	ADA	\$0
248843	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	Staff Unisex Restroom	ADA	\$0
248844	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Staff Unisex Restroom	ADA	\$481
248845	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	Staff Unisex Restroom	ADA	\$151

248846	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Unisex Restroom	ADA	\$467
248847	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	Staff Unisex Restroom	California Accessibility Code	\$1,799
248848	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	Staff Unisex Restroom	California Accessibility Code	\$368
248849	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	Staff Unisex Restroom	California Accessibility Code	\$1,447
248850	Windsor Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Staff Unisex Restroom	ADA	\$1,644
248857	Windsor Library	INTERIOR	Interior Access Route	Signage	3	Assistive listening signage is not compliant or is not provided.	Community Room	ADA	\$72
248950	Cloverdale Library	INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Staff Work Room	ADA	\$434
248955	Cloverdale Library	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	Main Entrance Lobby	California Accessibility Code	\$7,152
248956	Cloverdale Library	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	Main Entrance Lobby	California Accessibility Code	\$7,152
248959	Cloverdale Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	Men's & Women's Restroom	California Accessibility Code	\$1,894
248960	Cloverdale Library	INTERIOR	Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	Men's Restroom	ADA	\$1,230
248961	Cloverdale Library	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Men's & Women's Restroom	ADA	\$771
248962	Cloverdale Library	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Men's & Women's Restroom	ADA	\$771
248963	Cloverdale Library	INTERIOR	Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	Men's & Women's Restroom	ADA	\$302
248964	Cloverdale Library	INTERIOR	Restroom	Restroom/Bathroom - Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Men's & Women's Restroom	ADA	\$7,233
248965	Cloverdale Library	INTERIOR	Restroom	Controls And Dispensers	3	Controls on dispensers are not compliant.	Women's Restroom	ADA	\$263
248968	Cloverdale Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	Staff Unisex Restroom	California Accessibility Code	\$385
248969	Cloverdale Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width.	Staff Unisex Restroom	ADA	\$1,478
248970	Cloverdale Library	INTERIOR	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Staff Unisex Restroom	ADA	\$15,780
248973	Cloverdale Library	INTERIOR	Kitchen	Dining Table	3	CALIFORNIA: A compliant dining table is not provided.	Staff Break Room Kitchen	California Accessibility Code	\$1,710
248541	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	Unisex Restrooms	ADA	\$0
248542	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Unisex Restrooms	ADA	\$963
248543	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Unisex Restrooms	ADA	\$1,657
248544	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The push side of the door does not have the required maneuvering clearances.	Unisex Restroom East	ADA	\$1,644
248545	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Unisex Restroom East	ADA	\$412
248546	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	Unisex Restroom East	ADA	\$151
248552	Sebastopol Library	INTERIOR	Common Areas	Assembly Area	3	Assistive listening signage is not compliant or is not provided.	Community Room	ADA	\$72
248562	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Staff Unisex Restroom	ADA	\$481
248563	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	Staff Unisex Restroom	ADA	\$0

248564	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	Staff Unisex Restroom	ADA	\$151
248565	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	Staff Unisex Restroom	California Accessibility Code	\$368
248566	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	Staff Unisex Restroom	California Accessibility Code	\$947
248567	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	Staff Unisex Restroom	ADA	\$85
248568	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff Unisex Restroom	ADA	\$263
248569	Sebastopol Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	Staff Unisex Restroom	California Accessibility Code	\$0
248570	Sebastopol Library	INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Staff Break Room	ADA	\$869
248708	Sebastopol Library	INTERIOR	Kitchen	Sink	3	CALIFORNIA: The sink does not have the required clear floor space of minimum 30" by minimum 48" for a forward approach with knee and toe clearance.	Staff Breakroom Kitchen	California Accessibility Code	\$3,945
249260	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	Men's/ Women's Restroom RR1/RR2	ADA	\$963
249261	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Men's/ Women's Restroom RR1/RR2	ADA	\$0
249263	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	Men's/ Women's Restroom RR1/RR2	California Accessibility Code	\$1,894
249265	Northwest Santa Rosa Library	Interior	Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	Men's/ Women's Restroom RR1/RR2	California Accessibility Code	\$1,052
249268	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Men's/ Women's Restroom RR1/RR2	ADA	\$934
249269	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	Men's/ Women's Restroom RR1/RR2	California Accessibility Code	\$3,598
249270	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	Women's Restroom RR2	California Accessibility Code	\$368
249271	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	Men's/ Women's Restroom RR1/RR2	ADA	\$302
249272	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	Women's Restroom RR2	California Accessibility Code	\$145
249273	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Door	3	The hardware at the wheelchair stall door is not compliant.	Men's/ Women's Restroom RR1/RR2	ADA	\$771
249274	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet stall door is not compliant.	Women's Restroom RR2	California Accessibility Code	\$1,447
249286	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Unisex Restroom RR3	ADA	\$132
249288	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	Unisex Restroom RR3	ADA	\$151
249289	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	Unisex Restroom RR3	California Accessibility Code	\$132
249290	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Unisex Restroom RR3	ADA	\$412
249291	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Unisex Restroom RR3	ADA	\$467
249827	Northwest Santa Rosa Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	Men's/ Women's Restroom RR1/RR2	ADA	\$263
248741	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width.	Upper Floor Adult Literacy & Staff Restrooms	ADA	\$2,956
248742	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	Upper Floor Adult Literacy & Staff Restrooms	California Accessibility Code	\$771
248743	Central Library	INTERIOR	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Upper Floor Adult Literacy & Staff Restrooms	ADA	\$31,560

248749	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	Ground Floor Staff Restrooms	California Accessibility Code	\$771
248750	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width.	Ground Floor Staff Restrooms	ADA	\$5,912
248751	Central Library	INTERIOR	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Ground Floor Staff Restrooms	ADA	\$31,560
248754	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	Ground Floor Children's Library	California Accessibility Code	\$289
248756	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width.	Ground Floor Children's Library	ADA	\$2,956
248757	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: Maneuvering clearance at the door is not level and clear.	Ground Floor Children's Library	ADA	\$3,288
248758	Central Library	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Ground Floor Children's Library	ADA	\$7,233
248759	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	Ground Floor Children's Library	ADA	\$1,230
248764	Central Library	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Ground Floor Restrooms	ADA	\$771
248765	Central Library	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Ground Floor Restrooms	ADA	\$771
248766	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	Ground Floor Restrooms	California Accessibility Code	\$3,598
248767	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	Ground Floor Restrooms	California Accessibility Code	\$736
248769	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Ground Floor Restrooms	ADA	\$263
248783	Central Library	INTERIOR	Common Areas	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	Reading Garden	California Accessibility Code	\$1,710
248796	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width.	Staff Women's & Men's Restroom	ADA	\$5,912
248797	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Staff Women's & Men's Restroom	ADA	\$7,233
248798	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: Maneuvering clearance at the door is not level and clear.	Staff Women's & Men's Restroom	ADA	\$3,288
248799	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff Women's & Men's Restroom	ADA	\$526
248800	Central Library	INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Staff Women's & Men's Restroom	ADA	\$395
248801	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	Staff Women's & Men's Restroom	California Accessibility Code	\$1,894
248802	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	Staff Women's & Men's Restroom	ADA	\$171
248803	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	Staff Women's & Men's Restroom	California Accessibility Code	\$7,890
248805	Central Library	INTERIOR	Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	Staff Women's & Men's Restroom	California Accessibility Code	\$395
248806	Central Library	INTERIOR	Restroom	Controls And Dispensers	3	Controls on dispensers are not compliant.	Staff Women's Restroom	ADA	\$263
248808	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	Staff Men's Restroom	ADA	\$1,230
248809	Central Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	The lavatory faucet hardware is not compliant.	Staff Men's Restroom	ADA	\$730
248810	Central Library	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	Lower Level	California Accessibility Code	\$7,152
248811	Central Library	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	Lower Level	California Accessibility Code	\$7,152

248818	Central Library	INTERIOR	Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	Ground Floor Restrooms	California Accessibility Code	\$395
249120	Central Library	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	Ground Floor Children's Library	California Accessibility Code	\$1,894
249121	Central Library	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Ground Floor Children's Library	ADA	\$171
248101	Rohnert Park-Cotati Library	INTERIOR	Kitchen	Sink	3	CALIFORNIA: The sink does not have the required clear floor space of minimum 30" by minimum 48" for a forward approach with knee and toe clearance.	Community Room Kitchen	California Accessibility Code	\$3,945
248105	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Men's & Women's Restroom	ADA	\$526
248106	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The wheelchair stall door is not self closing.	Men's & Women's Restroom	ADA	\$771
248107	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Women's Restroom	ADA	\$467
248108	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	Men's & Women's Restroom	California Accessibility Code	\$3,598
248109	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Men's Restroom	ADA	\$947
248110	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Signage	3	The provided signage is not mounted at the latch side of the door or at a compliant height.	Men's & Women's Restroom	ADA	\$145
248112	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	Family Restrooms	ADA	\$963
248113	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Family Restrooms	ADA	\$0
248114	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Family Restrooms	ADA	\$934
248115	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	Family Restrooms	California Accessibility Code	\$3,598
248116	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	Family Restrooms	California Accessibility Code	\$368
248117	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Family Restrooms	ADA	\$526
248118	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	Family Restrooms	California Accessibility Code	\$2,893
248120	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	Staff Unisex Restrooms	ADA	\$963
248121	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Staff Unisex Restrooms	ADA	\$0
248122	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff Unisex Restrooms	ADA	\$263
248123	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	Staff Unisex Restrooms	California Accessibility Code	\$1,894
248124	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	Staff Unisex Restrooms	California Accessibility Code	\$2,893
248125	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Unisex Restrooms	ADA	\$467
248126	Rohnert Park-Cotati Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	Staff Unisex Restrooms	California Accessibility Code	\$1,799
248127	Rohnert Park-Cotati Library	INTERIOR	Kitchen	Sink	3	CALIFORNIA: The sink does not have the required clear floor space of minimum 30" by minimum 48" for a forward approach with knee and toe clearance.	Staff Kitchen	California Accessibility Code	\$3,945
248134	Rohnert Park-Cotati Library	INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Staff Lockers	ADA	\$434
248612	Rohnert Park-Cotati Library	INTERIOR	Common Areas	Assembly Area	3	Assistive listening signage is not compliant or is not provided.	Community Room & Conference Room	ADA	\$145
248021	Sonoma Valley Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	Men's Restroom	ADA	\$0
248022	Sonoma Valley Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Men's & Women's Restroom	ADA	\$963

248023	Sonoma Valley Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The hardware at the wheelchair stall door is not compliant.	Men's & Women's Restroom	ADA	\$771
248024	Sonoma Valley Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	Women's Restroom	California Accessibility Code	\$1,799
248031	Sonoma Valley Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Staff Unisex Restroom	ADA	\$481
248032	Sonoma Valley Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	Staff Unisex Restroom	California Accessibility Code	\$1,447
247961	Petaluma Library	INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Staff Entrance Corridor	ADA	\$434
247963	Petaluma Library	INTERIOR	Common Areas	Dining Table	3	CALIFORNIA: A compliant dining table is not provided.	Staff Breakroom	California Accessibility Code	\$1,710
247976	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Men's & Women's Restroom	ADA	\$0
247977	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	Men's & Women's Restroom	ADA	\$963
247978	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	Men's & Women's Restroom	California Accessibility Code	\$1,894
247981	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	Men's & Women's Restroom	California Accessibility Code	\$771
247982	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Men's & Women's Restroom	ADA	\$771
247983	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Men's & Women's Restroom	ADA	\$771
247985	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	Men's & Women's Restroom	California Accessibility Code	\$3,598
247986	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Men's & Women's Restroom	ADA	\$934
247987	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Men's Restroom	ADA	\$263
247992	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width.	Children's Unisex Restroom	ADA	\$2,956
247993	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	Children's Unisex Restroom	ADA	\$481
247994	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	Children's Unisex Restroom	ADA	\$85
247996	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom- Unisex	3	Less than 50% of multiple single user toilet rooms clustered at a single location are accessible.	Children's Unisex Restroom	ADA	\$3,945
247997	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Children's Unisex Restroom	ADA	\$1,644
247998	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width.	Staff Unisex Restroom	ADA	\$1,478
247999	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Staff Unisex Restroom	ADA	\$15,780
248000	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width.	Staff Women's Restroom	ADA	\$1,478
248001	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	Staff Women's Restroom	ADA	\$85
248002	Petaluma Library	INTERIOR	Restroom	Restroom/Bathroom - Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Staff Women's Restroom	ADA	\$3,616
248007	Petaluma Library	INTERIOR	Interior Access Route	Elevator	3	CALIFORNIA: An elevator is required but not provided.	2nd Floor	California Accessibility Code	\$105,200
248595	Petaluma Library	INTERIOR	Transient Lodging	Kitchen- U-Shaped or L-Shaped Layout	3	The U-shaped or L-shaped kitchen is not compliant.	Community Room	ADA	\$10,458
248596	Petaluma Library	INTERIOR	Kitchen	Sink	3	CALIFORNIA: The sink does not have the required clear floor space of minimum 30" by minimum 48" for a forward approach with knee and toe clearance.	Community Room	California Accessibility Code	\$3,945
249172	Rincon Valley Library	Interior	Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	Men's and Women's Restroom RR1/RR2	California Accessibility Code	\$3,288
249174	Rincon Valley Library	Interior	Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	Men's and Women's Restroom RR1/RR2	ADA	\$771

249175	Rincon Valley Library	Interior	Restroom	Restroom/Bathroom - Door	3	The hardware at the wheelchair stall door is not compliant.	Men's and Women's Restroom RR1/RR2	ADA	\$1,541
249178	Rincon Valley Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Men's and Women's Restroom RR1/RR2	ADA	\$934
249199	Rincon Valley Library	Interior	Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Staff Unisex Restroom RR3	ADA	\$132
249200	Rincon Valley Library	Interior	Restroom	Restroom/Bathroom - Lavatory	3	The lavatory does not have the required clear floor space of minimum 30" by minimum 48".	Staff Unisex Restroom RR3	ADA	\$3,945
249201	Rincon Valley Library	Interior	Restroom	Restroom/Bathroom - Lavatory	3	The lavatory faucet hardware is not compliant.	Staff Unisex Restroom RR3	ADA	\$730
249202	Rincon Valley Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	Staff Unisex Restroom RR3	California Accessibility Code	\$132
249203	Rincon Valley Library	Interior	Restroom	Controls And Dispensers	3	Controls on dispensers are not compliant.	Staff Unisex Restroom RR3	ADA	\$263
249204	Rincon Valley Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Unisex Restroom RR3	ADA	\$467
249205	Rincon Valley Library	Interior	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	Staff Unisex Restroom RR3	California Accessibility Code	\$1,447
249212	Rincon Valley Library	Interior	Interior Access Route	Sink	3	CALIFORNIA: The sink located adjacent the side wall /side partition does not have the required side clearance.	Kitchen	California Accessibility Code	\$132
249222	Guerneville Library	EXTERIOR	Accessible Parking	Parking Spaces-General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	Parking Lot 1	California Accessibility Code	\$368
249163	Rincon Valley Library	Exterior	Exterior Access Route	Signage	4	Signage identifying a permanent outdoor space does not have visual characters which comply with the height requirements, and/or does not have raised lettering and Braille.	Exterior Signs	ADA	\$1,473
249218	Rincon Valley Library	Exterior	Accessible Parking	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	Parking Lot	California Accessibility Code	\$368
247917	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	Parking Lot 1	California Accessibility Code	\$1,105
247937	Petaluma Library	EXTERIOR	Accessible Parking	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	Parking Lot 2	California Accessibility Code	\$368
247940	Petaluma Library	EXTERIOR	Exterior Access Route	Telephone	4	Clear floor space is not provided at the accessible public telephone	Public Telephone PT	ADA	\$313
247941	Petaluma Library	EXTERIOR	Exterior Access Route	Telephone	4	The highest operable part of the accessible public telephone is not compliant.	Public Telephone PT	ADA	\$526
248591	Petaluma Library	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	4	CALIFORNIA: The loading/unloading access aisle does not have compliant signage.	Parking Lot 1	California Accessibility Code	\$368
248080	Rohnert Park-Cotati Library	EXTERIOR	Accessible Parking	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	Parking Lot 1	California Accessibility Code	\$368
248602	Rohnert Park-Cotati Library	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	4	CALIFORNIA: The loading/unloading access aisle does not have compliant signage.	Main Entrance	California Accessibility Code	\$368
248989	Healdsburg Library	EXTERIOR	Accessible Parking	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	Parking Lot 1	California Accessibility Code	\$368
249242	Northwest Santa Rosa Library	Exterior	Accessible Parking	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	Parking Lot	California Accessibility Code	\$368
248941	Cloverdale Library	EXTERIOR	Accessible Parking	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	Parking Lot 1	California Accessibility Code	\$368
248724	Central Library	EXTERIOR	Accessible Parking	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	Parking Lot 1	California Accessibility Code	\$368

249011	Healdsburg Library	INTERIOR	Common Areas	Telephone	4	The highest operable part of the accessible public telephone is not compliant.	Main Entrance Lobby	ADA	\$526
249060	Healdsburg Library	INTERIOR	Kitchen	Kitchen- Appliance Controls	4	Appliance controls cannot be operated with one hand, require tight grasping, pinching, or twisting of the wrist, or require more than 5 pounds force to operate.	Staff Breakroom Kitchen	ADA	\$1,578
249061	Healdsburg Library	INTERIOR	Kitchen	Controls And Dispensers	4	Controls and/or dispensers are not within an allowable reach range.	Staff Breakroom Kitchen	ADA	\$1,444
248904	Guerneville Library	INTERIOR	Interior Access Route	Telephone	4	The highest operable part of the accessible public telephone is not compliant.	Main Entrance Lobby	ADA	\$526
248928	Guerneville Library	INTERIOR	Kitchen	Kitchen- Appliance Controls	4	Appliance controls cannot be operated with one hand, require tight grasping, pinching, or twisting of the wrist, or require more than 5 pounds force to operate.	Staff Breakroom Kitchen	ADA	\$1,578
248832	Windsor Library	INTERIOR	Interior Access Route	Telephone	4	The highest operable part of the accessible public telephone is not compliant.	Main Entrance Lobby	ADA	\$526
248972	Cloverdale Library	INTERIOR	Kitchen	Appliance	4	Appliance controls cannot be operated with one hand, require tight grasping, pinching, or twisting of the wrist, or require more than 5 pounds force to operate.	Staff Break Room Kitchen	ADA	\$1,578
248540	Sebastopol Library	INTERIOR	Common Areas	Telephone	4	The highest operable part of the accessible public telephone is not compliant.	Main Entrance Lobby	ADA	\$526
248571	Sebastopol Library	INTERIOR	Common Areas	Controls And Dispensers	4	Controls and/or dispensers are not within an allowable reach range.	Staff Break Room	ADA	\$395
248733	Central Library	INTERIOR	Interior Access Route	Elevator	4	CALIFORNIA: The elevator car dimensions are not compliant.	Staff Elevator	California Accessibility Code	\$105,200
248734	Central Library	INTERIOR	Interior Access Route	Elevator	4	CALIFORNIA: An elevator is required but not provided.	Public Area	California Accessibility Code	\$105,200
248753	Central Library	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	CALIFORNIA: The minimum number of drinking fountains is not provided.	Ground Floor Children's Library	California Accessibility Code	\$7,152
248755	Central Library	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	Ground Floor Children's Library	California Accessibility Code	\$7,152
248760	Central Library	INTERIOR	Interior Access Route	Telephone	4	The highest operable part of the accessible public telephone is not compliant.	Ground Floor	ADA	\$526
248794	Central Library	INTERIOR	Kitchen	Kitchen - Oven	4	Controls and/or dispensers are not within an allowable reach range.	Staff Kitchen	ADA	\$1,444
248795	Central Library	INTERIOR	Kitchen	Kitchen - Appliance Controls	4	Appliance controls cannot be operated with one hand, require tight grasping, pinching, or twisting of the wrist, or require more than 5 pounds force to operate.	Staff Kitchen	ADA	\$316
249137	Central Library	INTERIOR	Interior Access Route	Telephone	4	None of the telephones are TTY enabled.	Ground Floor	ADA	\$1,973
248103	Rohnert Park-Cotati Library	INTERIOR	Interior Access Route	Operable Part	4	The highest operable part of the accessible public telephone is not compliant.	Main Entrance Vestibule	ADA	\$658
248605	Rohnert Park-Cotati Library	INTERIOR	Kitchen	Kitchen- Range/Cooktop/Oven	4	The location of the controls requires reaching across burners.	Community Room Kitchen	ADA	\$998
248611	Rohnert Park-Cotati Library	INTERIOR	Kitchen	Kitchen- Range/Cooktop/Oven	4	The location of the controls requires reaching across burners.	Staff Kitchen	ADA	\$998
247975	Petaluma Library	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Main Entrance Vestibule	ADA	\$1,289
248597	Petaluma Library	INTERIOR	Kitchen	Kitchen- Range/Cooktop/Oven	4	The location of the controls requires reaching across burners.	Community Room	ADA	\$998
249167	Rincon Valley Library	Interior	Interior Access Route	Exterior Accessible Route-Signage	4	Signage identifying the name of a permanent indoor or outdoor space does not have raised lettering and/or visual characters.	Interior Signs	ADA	\$2,577
249180	Rincon Valley Library	Interior	Interior Access Route	Telephone	4	The highest operable part of the accessible public telephone is not compliant.	Main Lobby	ADA	\$526
249196	Rincon Valley Library	Interior	Interior Access Route	Range/Cooktop/Oven	4	Clear floor or ground space is not provided at the range/cooktop.	North Staff Area	ADA	\$132
249211	Rincon Valley Library	Interior	Interior Access Route	Refrigerator/Freezer	4	The clear floor space at the refrigerator/freezer is not positioned for a parallel approach to the space dedicated for the refrigerator/freezer with the centerline of the clear floor or ground space offset 24" maximum from the centerline of the dedicated space.	Kitchen	ADA	\$922

249224 Rincon Valley Library	Interior	Interior Access Route	Telephone	4	None of the telephones are TTY enabled.	Main Lobby	ADA	\$1,973
Total Barriers: 686, Total Cost: \$1,933,253								